N. M. OIL CONS. COMMISSION

Form 9-331 Dec. 1973

P. Q. BOX 1980 HOBBS, NEW MEXICO 88240

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	
	5. LEASE NM-0175774
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a differen eservoir. Use Form 9–331–C for such proposals.)	Plains Operating Area
	8. FARM OR LEASE NAME
1. oil gas other	Plains Operating Area 9. WELL NO.
2. NAME OF OPERATOR	6
Dorchester Gas Corporation 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME
P. O. Box 96, Hobbs, New Mexico 88240	Lusk Strawn
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	AREA sec. 21 T. 19 S., R. 32 E.,
AT SURFACE: 1980' FNL & 660' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Lea New Mexico
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. 30-025-20769
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3602 RDB
HOOT OR ACIDIZE EPAIR WELL ULL OR ALTER CASING IULTIPLE COMPLETE HANGE ZONES BANDON* Temporarily Abandon KOSWELL, NE	10 St Stinuau
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating any proposed work. If well is measured and true vertical depths for all markers and zones pertined. Workover unsuccessful, too much water production abandon this well, yet retain wellbore for potent recovery operations.	directionally drilled, give subsurface locations and ent to this work.)* On. Request authorization to tempor
8. I hereby certify that the foregoing is true and correct	Set @Ft.
8. I hereby certify that the foregoing is true and correct	February 2, 1982
8. I hereby certify that the foregoing is true and correct	February 2, 1982

JAMES A. GILLHAM DISTRICT SUPERVISOR