

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42 R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-01135

6. IF INDIAN, ALLOTTEE OR TRIBAL NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <i>Recompletion</i>	7. UNIT AGREEMENT NAME <i>PLAINS UNIT Federal</i>
2. NAME OF OPERATOR <i>PAN AMERICAN PETROLEUM CORPORATION</i>	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR <i>BOX 68, HOBBS, N. M. 88240</i>	9. WELL NO. <i>7</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>660' FNL x 760' FWL Sec 33 (Unit D, NW 1/4 NW 1/4)</i>	10. FIELD AND POOL, OR WELL NAME <i>WILDCAT DELAWARE</i>
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA	12. COUNTY OR PARISH
13. STATE	14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	16. LEA
17. N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Strawn Zone: Abandoned. Plugs; 1504. cement 11502'-382'; 1504 11330'-210'; 1504 10612'-492'. Set CI BPC 7700'. Bone Springs: Perforated 7657-59 & Squeezed behind 5 1/2" casing w/ 12550 cement. Perf: 7535'-45' w/ 20JSF acidized w/ 1500 gal 15% LSTNE. Evaluated. No show of oil or gas. : Propose to abandon by spotting 4000 cement across perf 7535-45'. (T-BS 7300') Cut, raise, pull 5 1/2" Cog from free point to approx 5100' and recement w/ 1500 gal. Delaware: Perforate 4860'-40' w/ 20JSF. Acidize w/ 500 gal. Evaluate.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*0+4- USGS-IV
1- NSO
1- SUSP
1- RRY*

*See Instructions on Reverse Side

APPROVED
NOV 13 1968
A. R. BROWN
DISTRICT ENGINEER