

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20904
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE
6. State Oil & Gas Lease No. LG605
7. Lease Name or Unit Agreement Name Lusk 16 State
8. Well No. 002
9. Pool name or Wildcat Lusk Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Ray Westall	
3. Address of Operator P.O. Box 4 Loco Hills, NM 88255	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Section <u>16</u> Township <u>19South</u> Range <u>32East</u> NMPM Lea	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Re-Completion in Morrow

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/16/98 Rigged up Reverse unit.

12/28/98 Squeezed Bone Spring perfs 9326 - 9407 w/100 sxs "H."

1/13/99 Cleaned out to 12,814.

3/8/99 RIH w/ 2 3/8 tubing set packer @ 12485 pressure 5 1/2" CSNG to 900 # held 20 min.

3/11/99 Swab test existing perfs 12569 - 12729.

3/17/99 Acid w/1000 gal 7 1/2 HCL.

4/7/99 Flow 150 MCF 8 bbl condensate wait on gas hook up.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy Harris TITLE Geologist DATE 6/17/99

TYPE OR PRINT NAME Randy Harris

TELEPHONE NO. 677-2370

(This space for State Use)

APPROVED BY _____ TITLE PAUL F. KAUTZ DATE 2-9-2003

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER