Form 9-331 (May 1963)	UNITED STATES  SUBMIT IN TRIPLIC'TE*  OF THE INTERIOR (Other instructions re- re- property of the property of			Budg	Form approved. Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO. NM 0319697		
				וצט אמו			
					6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)							
OIL WELL GAS WELL OTHER					7. UNIT AGREDMENT NAME		
2. NAME OF OPERATO	)B	<b>3.</b> W	oct 2 6 1964	8. FARM OR L	EASE NAME		
Tenneco Oil Company					USA-Hudson		
3. ADDRESS OF OPERATOR					9. WELL NO.		
Por 1021 Midland Marca					<b>1</b>		
Box 1031, Midland, Texas 46633.  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.					10. FIELD AND POOL, OR WILDCAT		
See also space 17 At surface	below.)			7 Translation and			
1980' FNL & 660' FWL of Section 5					Undesignated 11. SEC., T., R., M., OR BLK. AND		
					SURVEY OR AREA		
14. PERMIT NO.		I If new (Cl )			'-19-S, R-32-	-E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF	, , ,,	12. COUNTY O	R PARISH 13. STATE		
· · · · · · · · · · · · · · · · · · ·		3658 GL Estin	nated	Lea_	New Me	xico	
16.	Check Ap	opropriate Box To Indicate N	lature of Notice, Report, or	Other Data			
	NOTICE OF INTEN	TION TO:	SUBSEC	QUENT REPORT OF	:		
MPCM WAMED CIT			T-1			1	
TEST WATER SHU	[	PULL OR ALTER CASING	WATER SHUT-OFF	REI	AIRING WELL		
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT	AL1	ERING CASING		
SHOOT OR ACIDIZ	E	ABANDON*	SHOOTING OR ACIDIZING	ABA	NDONMENT*		
REPAIR WELL	<u> </u>	CHANGE PLANS	(Other)	o of multiple son			
(Other)	- <u></u>		(Note: Report result Completion or Recom	pletion Report an	d Log form.)		
17. DESCRIBE PROPOSE proposed work. nent to this wor	it well is direction	RATIONS (Clearly state all pertinen nally drilled, give subsurface locat	t details, and give pertinent dates tions and measured and true verti-	s, including estim cal depths for all	ated date of starting markers and zones	g any perti-	
				•		\$	
Spudded 17 1.	/2" hole 9:0	0 P.M. MST 10-17-64.	Set and omta 12 2/	8" OD 1.9/			
	- 1.010 ).0	0 1 114 125 120-11-04.	Sec and emid 13 3/	0 OD, 40#	csg at 686'	with	
600 sx 50-50	- Posmir Inc	on ant rath od on a	Out of a	_		7	
000 BR 70-70	- FOZMIX INC	or emt with 2% CaCl 2	Cmt circulated.	Pressure t	ested csg	Por 3	
+= 1000 PGT -	0 20	<b>3</b> / <b>330 30 .</b>					
to 1000 PS1 3	for 30 mins	after WOC 18 hrs. H	eld OK.				
			·				

\*See Instructions on Reverse Side 6 1964

J. L. GORDON ACTING DISTRICT ENGINEER