Form 9-531 (May 1907)						
	_	ICES AND REPORTS sals to drill or to deepen or plug ATION FOR PERMIT—" for such	- · · · · ·	6. IF INDIAN, ALLO	TIER OR TRIBE NAME	
OIL X GA	other	7. UNIT AGREEMENT NAME				
2. NAME OF OPERAT	OK.	8. FARM OR LEASE NAME				
Tenneco Off Company 3. Address of Operator				USA-Trigg "C" Unit		
		1				
Box 1031, M	Laland, Texa	10. FIELD AND POOL, OR WILDCAT				
See also space 17 At surface		Undesignated				
1980' FNL & 660' FWL of Section 8				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
				Sec. 8, T-1	9-S,R-32-E	
14. PERMIT SO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PAR	ISH 13. STATE	
		3644 DF		Lea	New Mexico	
16.	Check A	opropriate Box To Indicate	Nature of Notice, Report, or	Other Data		
	NOTICE OF INTE	ITION TO:	SUBSE	QUENT REPORT OF:		
TEST WATER SH FRACTURE TREAT SHOOT OR ACIDIS REPAIR WELL	,	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	ABANDON	G CASING X	
(Other)				its of multiple completion on Well apletion Report and Log form.)		
17. DESCRIBE PROPOSI proposed work nent to this wo	. If well is directi	RATIONS (Clearly state all pertino onally drilled, give subsurface loc	ent details, and give pertinent dates cations and measured and true verti-	s, including estimated cal depths for all mar	date of starting any kers and sones perti-	
Well has be	en plugged a	nd abandoned as fol	lows:	•		
	csg. cut an		3.2. · · · · ·			
75 sx cmt. plug set 700-600'						
			Casing and dry hole	marker erecte	d.	
		otted between plugs			4	
			' of 13 $3/8$ " csg. lef	t in hole.		
		bandoned March 11,				
This final	plugg <b>ing rep</b>	ort supplements the	plugging report subm	itted Novembe	r 11,1964.	
					ţ	

APPROVED

\*See Instructions on Reverse Side APR - 2 1965