

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

CONSERVATION DIVISION

P. O. BOX 2089

SANTA FE, NEW MEXICO 87501

Form 1-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. B-1080-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

TEXACO Inc.

Address of Operator

Drawer 728, Hobbs, New Mexico 88240

Location of Well

UNIT LETTER C 1880 FEET FROM THE West LINE AND 460 FEET FROM

THE North LINE, SECTION 1 TOWNSHIP 18-S RANGE 34-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

4006' (DF)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

OTHER Set add'l. plugs in P&A well ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pulled 2-7/8" tubing from cement retainer at 1395'.
2. Set 175 sx. Class "H" cement plug from 1395-1095'.
3. Spot 25 sx. Class "H" cement plug from 50' to surface.
4. Install dry-hole marker. Clean location.
5. Return to P&A status 10-22-80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Ass't. Dist. Supt.

DATE

10-23-80

APPROVED BY

TITLE

OIL & GAS INSPECTOR

DATE

JUN 23 1981

CONDITIONS OF APPROVAL, IF ANY: