Submit 3 Copies To Appropriate District	State of New Me	xico	_	Form C-103
Office	Energy, Minerals and Natural Resources			Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	Enorgy, Transcript		WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-025 Z0979-6 ⁻ 5. Indicate Type of Lease	
811 South First, Artesia, NM 88210	2040 South Pacheco		, · · · · · · · · · · · · · · · · · · ·	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🔀	FEE L
District IV			6. State Oil & Gas I	
2040 South Pacheco, Santa Fe, NM 87505			E-77	
SUNDRY NOTI	CES AND REPORTS ON WELLS	IC DACV TO A	7. Lease Name or Ur	iit Agreement Name.
THE FORM FOR PROPO	GALS TO DRILL OR TO DEEPEN OK PLU	JG BACK TO A	ļ	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		STATE AF		
1. Type of Well:	Ou h		OTHE NI	
Oil Well Gas Well	Other SwD		0 W-UN- 0	
		8. Well No. 2	·	
2. Name of Operator PENROC OIL CORPORATION 8. WEIL			9. Pool name or Wile	dcat
3. Address of Operator 0.10	BOX 5970, HOBBS,	NN88241	Vacuum	Wolfcomp
	100 x 37 /0, 1212237		V 000 0001111	
4. Well Location				
	2130 feet from the EAS	line and	330 feet from t	he South line
Unit Letter:	eet from the			Y .
Section 8	Township 185 Ra	$_{\rm inge}$ 35 \in	NMPM LEA C	County
Section <u>8</u>	10. Elevation (Show whether D.	R, RKB, RT, GR, et	c.)	
11 Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Da	ıta
NOTICE OF IN	ITENTION TO:	SUE	こうにいいこい コントレ	
PERFORM REMEDIAL WORK	1 PLUG AND ABANDON 🗆	REMEDIAL WOF		ALTERING CASING \square
PERFORM REMEDIAL WORK	1 1 200 / 1145 / 107 11 20 1			
TEMPORARILY ABANDON	CHANGE PLANS 🔲	COMMENCE DR		PLUG AND ABANDONMENT
TEIM OLD WILL TO THE STATE OF	_	CASING TEST A		ADAMOCHMENT
PULL OR ALTER CASING L	MULTIPLE	CEMENT JOB		
	COMPLETION	022		
OTHER:		OTHER:		
	eted operations. (Clearly state all pe	rtinent details, and	give pertinent dates, in	cluding estimated date
OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.				
11 21/2 + bay. Det CIBP on				
la to via up and pull 3/2 clay 4 pri				
Tian by the state of the state				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atlacti we mode that agrain of proposed completions. Plan to rig up and pull 31/2 tlog & pkr. Set CIBP on whine @ 9800 w 35' coment via dump bailer. TIH w whine @ 9800 w 35' coment via dump bailer. TIH w tubing displace hole w plan fluid. Pressure test to 500 - get MIT chart - Rig dam -				
William Is I have the total				
I live displace hole w/ Play				
tubing the Ria dum-				
L FOR get MII charl - 17				
10 200 -	Q .		•	
TOP PERF	981.4			
70P PERF	(00)			•
•				
42.3	is two and complete to th	e hest of nov knowl	edge and belief.	
I hereby certify that the informat	ion above is true and complete to the		n L	7/7/00
SIGNATINE I	TITLE	Bend		_DATE/ / / 00
SIGNATURE				none No. 397-3596
Type or print name	1. Merchant		Teleph	ione No.
(This space for State use)		THE STATE OF THE S	4.	
(This space for state use)	11.00		*:	DATE
APPPROVED BY Law	W. Wink TITLE			_DATE
Conditions of approval; if any:				
\	!			

