Form	9-331
(May	1963)

 $\overline{2}$.

3.

4.

14.

16.

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

SUBMIT IN TRIPLI (Other instructions on

Form approved. Budget Bureau No. 42-R1424.

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

GEOLOGICAL SURVEY		NM-23007	5. LEASE DESIGNATION AND SERIAL NO. NM-23007		
(Do not use this form for pro	OTICES AND REPORTS Coposals to drill or to deepen or plug by ICATION FOR PERMIT—" for such pro-	ick to a different reservoir.	6. IF INDIAN, ALL	OTTEE OR TRIBE NAME	
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME		
NAME OF OPERATOR		8. FARM OR LEASE NAME			
C & K Petroleum, Inc.			9. WELL NO.	Greenwood "6" Federal 9. WELL NO.	
P. O. Drawer 3546 Midland, Texas 79702 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		#1 10. FIELD AND POOL OR WILDCAT			
	FS Lines, Sec. 6, T-19-	S, R-32-E, Eddy	North Lus 11. SEC., T., R., M. SURVEY OR	OR BLK. AND	
		•	Sec. 6. 5	r-19-s, R-32-E	
PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		RT, GR, etc.)	12. COUNTY OR PA	ARISH 13. STATE	
	3644 Gr.		Lea	New Mexico	
Check .	Appropriate Box To Indicate N	ature of Notice, Report, o	or Other Data		
NOTICE OF INTENTION TO:		SUB	SEQUENT REPORT OF:	* * * * * * * * * * * * * * * * * * *	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIR	ING WELL	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

9/5/80 Move in and rig up Plugging unit. Plug #1 - 15 sx. Cl."C" 11300 - 11150' Cut 5-1/2" casing. Recovered 204 Jts., 8514' left 3959' in hole.

9/6/80 Plug #2 - 30 sx. Cl. "C" 8600 - 8450' Plug #3 - 40 sx. Cl. "C" 5425 - 5275' Plug #4 - 30 sx. Cl. "C" 3600 - 3500' Plug #5 - 30 sx. Cl. "C" 3200 - 3100' Plug #6 - 20 sx. Cl. "C" 15' - Surface Erected P & A Marker. Job complete 9/6/80

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

RECEIVED 10 1980 da

	U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO
18. I hereby certify that the foregoing is true and correct	WEXICO
SIGNED TITLE Adm. Supervisor	DATE9/9/80
(This space for Federal of State office use)	
APPROVED BY (Orig. Sgd.) PETER W. CHESTER ACTING DISTRICT ENGI	NEER DATE NOV 1 4 1980
CONDITIONS OF APPROVAL, IF ANY:	