

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

COPIES OF THIS FORM		
DISTRIBUTION		
DATE		
BY		
TO		
FROM		
REMARKS		

3a. Indicate Type of Lease
State ☒ Fee ☐
3. State Oil & Gas Lease No.
B-1306-1

SUNDY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SALS TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

☒ GAS WELL ☐ OTHER		7. Unit Agreement Name
4. Operator TEXACO INC. 5. Address of Operator P.O. BOX 728, HOBBS, N.M. 88240		8. Form or Lease Name New Mexico "R" State NCT 9. Well No. 16
6. Location of Well LETTER I 1655 FEET FROM THE South LINE AND 330 FEET FROM East LINE, SECTION 1 TOWNSHIP 18S RANGE 34E NMPW.		10. Field and Pool, or Wildcat Vacuum Grayburg San Andr
11. Elevation (Show whether DF, RT, CR, etc.) 3996' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

☐ REMEDIAL WORK ☐ ABANDON ☐ ALTER CASING ☐ PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER	☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPER. ☐ CASING TEST AND CEMENT JOBS ☐ ALTERING CASING ☒ PLUG AND ABANDONMENT ☐ OTHER
---	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations.) SEE RULE 1103.

- Rigged up.
- Set CIBP and set at 5950'. Dump 35' cmt. on top of plug.
- Set CIBP and set at 4755'. Cmt. 35' on top of plug. P&A New Mexico "R" State NCT-3 #16 and recompleted as Vacuum Grayburg San Andrew Unit, Well #68.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

W. B. Loh

TITLE Dist. Opr. Mgr.

DATE 9/30/85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DATE OCT 3 - 1985