

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Marathon Oil Company	5. State Oil & Gas Lease No. 384
3. Address of Operator P. O. Box 2409, Hobbs, New Mexico, 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>F</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>18S</u> RANGE <u>35E</u> N.M.P.M.	8. Farm or Lease Name Warn State A/C 2
	9. Well No. 15
	10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) GL 3976', KDB 3987'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marathon Oil Company intends to plug and abandon the Warn State A/C 2 Well No. 15 in the following matter, if it meets with the Oil Conservation's approval:

- 1) A cast iron bridge plug will be set at 6000' with 5 sacks of Class "C" cement containing 2% CaCl₂ placed on top of the plug. The well is perforated presently from 6046' - 6182' selectively.
- 2) The hole will then be circulated with 9.5#/gallon mud to surface. A Cement Bond Log will then be run to insure that cement covers the San Andres Formation.
- 3) A 20 sack cement plug will be placed from 4211' to 4011' which is the top of the Grayburg.

(continued)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven A. Pohler Steven A. Pohler TITLE Production Engineer

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

DATE September 27, 1985

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE OCT 1 - 1985