Submit 3 Copies to Appropriate District Office

State of New Mexico
Minerals and Natural Resources Department Enea

Form C-103 Revised 1-1-89

DISTRICT! OIL CONSERVATION DIVISION 5	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30-025-21623
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No. K-3851
SUNDRY NOTICES AND REPORTS ON WELLS	
(FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
I. Type of Well: Oil. GAS WELL X WELL OTHER	Lea 946 State
	8. Well No.
Devon Energy Corporation (Nevada) . Address of Operator	#1 9. Pool name or Wildcat
20 North Broadway Suite 1500 Oklahoma City, OK 73102	Buckeye ABO
Mell Location	Buckeye Abo
Unit Letter E: 1980 Feet From The North Line and 660	Feet From The West Line
Section 2 Township 18S Range 35E N	MPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3902 'G.R.	
	port, or Other Data
	01, 01 01101 211
11. Check Appropriate Box to Indicate Nature of Notice, Rep	EQUENT REPORT OF:
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBS	
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBS	EQUENT REPORT OF: ALTERING CASING
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBSERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OF THE PROPRIES COMMENCE DRILLING OF THE PLANS	EQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBSERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OF CASING TEST AND CEM	EQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBS ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEMPOTHER: OTHER: OTHER: WORKOVER	EQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT ENT JOB re-entry of P&A X
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBS ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEM OTHER: Workover 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including the completed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including the completed Operations (Clearly state all pertinent details, and give pertinent dates, including the completed Operations (Clearly state all pertinent details, and give pertinent dates, including the completed Operations (Clearly state all pertinent details, and give pertinent dates)	ALTERING CASING PLUG AND ABANDONMENT ENT JOB re-entry of P&A g estimated date of starting any proposed s and CIBP in this well. We ely perforated the ABO formare acidized with 1,500 gals was tested. We opened the
Check Appropriate Box to Indicate Nature of Notice, Rep NOTICE OF INTENTION TO: SUBS ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEMPOTHER: OTHER: OTHER: OTHER: OTHER: Workover 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103. On 11/2/92, we began drilling out the retainer, cement plug drilled out to a new TD of 8,995'. On 11/8/92, we selective tion from 8,887' - 8,928' (2 spf). The new perforations we 15% NEFE HC1 Acid. The load was swabbed back and the well	ALTERING CASING PLUG AND ABANDONMENT ENT JOB re-entry of P&A g estimated date of starting any proposed s and CIBP in this well. We ely perforated the ABO formare acidized with 1,500 gals was tested. We opened the
Check Appropriate Box to Indicate Nature of Notice, Ref NOTICE OF INTENTION TO: SUBS ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING	ALTERING CASING PLUG AND ABANDONMENT ENT JOB re-entry of P&A g estimated date of starting any proposed s and CIBP in this well. We ely perforated the ABO formare acidized with 1,500 gals was tested. We opened the 1/92 was:
Check Appropriate Box to Indicate Nature of Notice, Report NOTICE OF INTENTION TO: SUBS ERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING COMMENCE	ALTERING CASING PLUG AND ABANDONMENT ENT JOB re-entry of P&A g estimated date of starting any proposed s and CIBP in this well. We ely perforated the ABO formare acidized with 1,500 gals was tested. We opened the 1/92 was:
Check Appropriate Box to Indicate Nature of Notice, Ref NOTICE OF INTENTION TO: SUBS ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING	ALTERING CASING PLUG AND ABANDONMENT ENT JOB re-entry of P&A g estimated date of starting any proposed s and CIBP in this well. We ely perforated the ABO formare acidized with 1,500 gals was tested. We opened the 1/92 was: