## STATE OF NEW MEXICO



## ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

## OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

BRUCE KING GOVERNOR February 8, 1994

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

Southland Royalty Co.		
P 0 Box 51810		
Midland, TX 79710	·	
RE: CORRECTING API NUMBERS		
Gentlemen:		
The Oil Conservation Division each well on operators C-115 discovered incorrect API number on the federal well(s API records on file with the	report. As a resumbers on some feder listed below does	alt of this we have al wells. The API not agree with the
LEASE NAME, #, LOCATION Federal M	INCORRECT API #	CORRECT API #
#1-L, Sec. 27, T-18, R-33	30-025-16490	30-025-21895

We need you as the operator of the well to file a Federal Sundry Notice (Form 3160-5) to the appropriate BLM office stating the correct API # and requesting the API # be corrected in their records. You need to advise them this corrected number was obtained for the Oil Conservation Division. Also asking for the effective date when you may start using the correct number on BLM & MMS forms. If there is any questions, please call the Oil Conservation Division, District I Hobbs, NM (505) 393-6161.

Yours very truly,

OIL CONSERVATION DIVISION

Jerry Sexton

District I, Supervisor

JS:dp.

CC: BLM, Santa Fe, well file

