Form 9-331 (May 1963)

COPY TO O. C. C. UNITE STATES

SUBMIT IN TRIPLICAT

Form approved. Budget Bureau No. 42-R1424.

|--|

224) 2000)	DEPARTMENT C. T	HE INTERIO	R verse side)	5. LEASE DESIGNA	TION AND SERIAL NO.	
	GEOLOGICAL	SURVEY		LC-06494		
=	SUNDRY NOTICES AND	REPORTS OF	J WFIIS	6. IF INDIAN, ALLO	TTEE OR TRIBE NAME	
	se this form for proposals to drill or to Use "APPLICATION FOR PERM					
	Use "APPLICATION FOR PERM	III—" for such prop	osais.)	7. UNIT AGREEMEN	TNAME	
	VELL X OTHER Dry hole			I. OF IT AGREEMEN	1 NAME	
WELL V		2		8. FARM OR LEASE	NAME	
Southland Royalty Company				Federal	L "M"	
ADDRESS OF OPERATOR				9. WELL NO.		
		idland, TX		1	1	
LOCATION OF WELL (Report location clearly and in accordance with any St See also space 17 below.)			ite requirements.	10. FIELD AND POO	_	
At surface 1980' FSL & 990' FWL				11. SEC., T., R., M.,	ated (Wolfcamp)	
	1300 151 4 330 1 11	_	•	SURVEY OR	AREA	
					-18-S,R-33-E	
14. PERMIT NO.		(Show whether DF, RT	c, GR, etc.)	12. COUNTY OR PA		
	3805	KB		Lea	NM	
6.	Check Appropriate Box	To Indicate Nat	ure of Notice, Report, or	Other Data		
	NOTICE OF INTENTION TO:	I	SUBS	EQUENT REPORT OF:		
TEST WATER	SHUT-OFF PULL OR ALTER CA	SING	WATER SHUT-OFF	REPAIR	NG WELL	
FRACTURE TRE	<u> </u>		FRACTURE TREATMENT		VG CABING	
SHOOT OR ACI	DIZE ABANDON*		SHOOTING OR ACIDIZING		NMENT*	
REPAIR WELL	CHANGE PLANS		(Other) Plug bac	ck to Wolfca	amp X	
(Other)	(0)		Completion or Recor	mpletion Report and Lo	g form.)	
7. DESCRIBE PROPO proposed we nent to this	OSED OR COMPLETED OPERATIONS (Clearly ork. If well is directionally drilled, give	state an pertinent of subsurface location	is and measured and true ver	tical depths for all ma	rkers and zones perti-	
10-7-78 10-8-78	Install 35' cement GR Collar log. Per	MI&RUPU. Load hole w/KCl water, POH. Set CIBP @ 12,200'. Install 35' cement on top of BP @ 12,165'-12,200'. Run GR Collar log. Perf 10,664-672' w/2 SPF (Wolfcamp). GIH w/tbg & pkr, set pkr @ 10,525'. Acidize perf 10,664-				
20 0 70	674' w/1000 gals.					
10-9-78	Swab.					
10-10-78	Swab. Rec all load	Swab. Rec all load water + 22 bbls. salt water.				
10-11-78	Swab. Rec 15 bbls Well shut in waitin		r; fluid level her development		PU.	
- :) ;		•				
- 1		·	The Transfer of the Party of th	25		
1 5. 120 1 1	LUMEAL BURVEY TOPY OF SHOP	aba.	44.			
R. I hereby certif	y that the foregoing is true and correct					
	Harvey Par	D.	strict Engineer	7047	10-12-78	
SIGNED	A COURT	TITLE D1				
(This space for	r Federal or State office use)		ACCEPTED !	LOW WELL	K	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:			NON	3 1910 PVEY	//	
			n Reverse Side HOBBS,	NEW MEXICO	7	
	*9	pee Instructions o	n Reverse Side HOBBS			