

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 21 2:57 PM '68

5. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mar-Win Development Co.	8. Farm or Lease Name Atlantic-Richfield
3. Address of Operator P. O. Box 507 Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER 2310 FEET FROM THE N LINE AND 2310 FEET FROM THE W LINE, SECTION 15 TOWNSHIP 18 RANGE 38 NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3642 GR 3652 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Drilled to TD 4970' Ran Acoustic Velocity Log to 4965'
Set Plugs at following depths-**

**25 sx @ 4970'
25 sx @ 4700'
25 sx @ 3200'
25 sx @ 2000'
10 sx @ surface**

Dry hole marker set in 8-5/8" Casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L.H. Marshall

TITLE President

DATE Aug. 16, 1968

APPROVED BY John W. Runyon

TITLE Geologist

DATE JUN 1 1970

CONDITIONS OF APPROVAL, IF ANY: