

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>A-1543</b>	
7. Unit Agreement Name	
8. Farm or Lease Name <b>Gulf State</b>	
9. Well No. <b>1</b>	
10. Field and Pool, or Wildcat <b>Ark. Jct. - San Andres</b>	
12. County <b>Lea</b>	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>AZTEC OIL &amp; GAS COMPANY</b>
3. Address of Operator <b>P. O. Box 837, Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>J</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>12</b> TOWNSHIP <b>18-S</b> RANGE <b>36-E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3796 DF</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was Plugged and Abandoned as follows:

1. Tagged bottom at 5155'. Spotted 25 sx. cement plug from 5155-4940' (est.).
2. Circulated hole w/Mud Laden Fluid. Spotted 25 sx. cement plug from 4080-3865' (est.).
3. Cut casing at 2440' and 2030', could not pull. Ran tubing and spotted 25 sx. cement plug from 2067'-1852'.
4. Cut casing at 1462', could not pull.
5. Cut casing at 1262' and pulled out of hole.
6. Ran tubing to 1300' and spotted 25 sx cement plug from 1300'-1200'.
7. Spotted 25 sx cement plug 50' below casing shoe at 357'.
8. Spotted 10 sx cement plug in top of Surface.
9. Installed Dry Hole Marker and leveled location.

Work completed 1/25/73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>original signed by</u> <b>LESTER L. DUKE</b>	TITLE <u>District Superintendent</u>	DATE <u>June 11, 1973</u>
APPROVED BY <u><i>John W. Runyan</i></u>	TITLE <u>Chief</u>	DATE <u>June 11, 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		