

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O.C.C.
NEW MEXICO OIL CONSERVATION COMMISSION
APR 14 2 18 PM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
NM-2056

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Graham State (NCT-A)
3. Address of Operator Box 670, Hobbs, New Mexico 88240	9. Well No. 5
4. Location of Well UNIT LETTER H , 1980 FEET FROM THE North LINE AND 760 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 18-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3668' OL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6107' TD, 6086' PB.

Moran Drilling Company reached TD of 7-7/8" hole at 3:00 AM, April 10, 1969. Ran 192 joints and 1 cut joint, 6095' of 5-1/2" 15.5# K-55 ST&C casing. Shoe at 6106', DV tool at 4649'. Cemented with 260 sacks of Class C neat. Open DV tool. WOC & circulated 4 hours. Cemented thru DV tool with 125 sacks of Class C with 16% gel, 2% salt, .2% TIC and 100 sacks of Class C neat. WOC 7 hours. TS indicated TOC at 4220'. WOC & NU 19-1/2 hours. Tested casing with 1000#, 30 minutes, OK. Drilled DV tool and tested with 1000#, 30 minutes, OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. D. BORLAND TITLE Area Production Manager DATE April 14, 1969
APPROVED BY [Signature] TITLE SUPERVISOR DATE
CONDITIONS OF APPROVAL, IF ANY: