Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATE. DEPARTME T OF THE INTERIOR (Other instructions on re- verse side) GELLOGICAL SURVEY					n re-	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.		
							LC-032233 (A)		
SUNDRY NOTICES AND REPORTS, ON WELLS (Do not use this form for proposals to drill or to deepen of play back to a different forservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)							6. IF INDIAN, ALLOTTEE OR FRIBE NAME		
1. OIL GAS WELL X WE			Jun 6	12 42	AM '69	7.	UNIT AGREEMENT	NAME	
2. NAME OF OPERATO							FARM OR LEASE I	NAME	
Humble Oil & Refining Company							Bowers A Federal		
3. ADDRESS OF OPER	ATOR	, <u> </u>				9.	WELL NO.		
 Box 1600, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FWL - 2150' FSL 							29 10. FIELD AND POOL, OR WILDCAT		
							Hobbs Blinebry 11. sec., T., R., M., OB BLK. AND SUBVEY OR AREA S29, T18S, R38E		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)							· ·		
IT. FERMIN NO.			now whether b	F, RT, GR, etc .	.)		COUNTY OR PAR		
16.		Later	1 1			!.T€		New Mexico	
10.			o Indicate I	Nature of	Notice, Report,	or Other	Data		
	NOTICE OF INTENT	ION TO:	r1		នប	BSEQUENT 1	REPORT OF:		
TEST WATER SHU		CLL OR ALTER CASE	1G		TER SHUT-OFF	<u>X</u>	REPAIRIN	G WELL	
FRACTURE TREAT SHOOT OR ACIDIZ	<u> </u>	ULTIPLE COMPLETE BANDON*			CTURE TREATMENT DOTING OR ACIDIZING	, <u>x</u>	ALTERING ABANDON 1		
REPAIR WELL	11	HANGE PLANS			ther) Perforat			11	
(Other)					(NOTE: Report re Completion or Re	completion	Report and Log	form.)	
17. DESCRIBE PROPOSE proposed work. nent to this wor	II wen is direction	ATIONS (Clearly sta ally drilled, give s	te all pertiner ubsurface loca	it details, a itions and n	nd give pertinent on measured and true v	dates, inclu vertical dep	ding estimated of the for all mark	late of starting any ers and zones perti-	
Drilled to T cemented wit 200 sacks Ir Perforated 4 total 15 jet at 5905. Pk acid. Max 2 Spotted acid Ran tbg. and well. Prepa	th 250 sacks acor Class C 1/2" casin ts. Ran tbg tr. @ 5880. 2800. Avg r across per set @ 5948	Trinity L WOC 24 g withl l with ret Loaded ho ate 2 bbls forations Swbd ac	ite cmt hrs. T RASF je rievabl le w/43 /min. 5831-37 id and	w/1/2 ested v t per t e bridge bbls b Bridge . Max	# Flocele p w/1000# for foot from 5 ge plug and prine water plug to 58 2500. Avo	ber sac 30 mi 5831-37 1 hook 5. Cir 860 and 1 rate	k follow n, held 7, 5870-7 wall pack culated l reset pl 2.4 bbls	ed with OK. 5, 5886-89, ker set 500 gals kr @ 5826.	
								1 1 3-	
							성숙이 가 위험 18월 - 19일 원임		
				•					
						÷			
18. I hereby certify t	hat the foregoing is	true and correct							
SIGNED D. L		mer	TITLE	Unit H	lead	· · ·	DATE 6-4	-69	
(This space for F	ederal or State office	use)							
APPROVED BY CONDITIONS OF	APPROVAL, IF AN	¥:	TITLE		· · · · · · · · · · · · · · · · · · ·		DATE		
	,							•** •	

1

*See Instructions on Reverse Side