

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23204
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SEC 31
2. Name of Operator SHELL WESTERN E&P INC.	8. Well No. 412
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter A : 660 Feet From The NORTH Line and 660 Feet From The EAST Line Section 31 Township 18S Range 38E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3651' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: PB, OAP, AT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-21-88 to 3-29-89

DO CIBP @ 4022, KNOCKED DOWN TO 4212'. RIH WITH CMT RETAINER & SET @ 4165'. SQZD SAN ANDRES PERFS 4174-4246' WITH 100 SX CLASS C CMT. LEFT 24 SX CMT ON TOP OF RET. DO CMT TO TOP OF RET @ 4165'. PT SQZD PERFS TO 500#, HELD OK. PERFED SAN ANDRES @ 4140', 43' AND 51' WITH 2 JSPF. RIH WITH PKR & SET @ 4138'. ACD PERFS 4134-51' WITH 1100 GAL 15% NEFE ACID. POH WITH PKR. RIH WITH PROD EQUIP. RETD TO PROD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE PROD. ADMIN. ADVISOR DATE MAY 08 1989
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 15 1989

CONDITIONS OF APPROVAL, IF ANY: