

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.

30-025-23221

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		6. State Oil & Gas Lease No. 28992
2. Name of Operator Texland Petroleum - Hobbs, L.L.C		7. Lease Name or Unti Agreement Name H.D. McKinley
3. Address of Operator 777 Main Street, Ste 33200 Fort Worth, Tx. 76102		8. Well No. 9
4. Well Location Unit Letter G : 2235 feet from the North line and 2310 feet from the East line Section 30 Township 18S Range 38E NMPM County Lea		9. Pool name or Wildcat Hobbs Blinebry
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3653' GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐
OTHER: Set CIBP to isolate Drinkard from Blinebry ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

12/11/01 MI BOF WSU. NU BOP. TIH w/6-1/8 bit, 6 3-1/2 DC & 2-3/8"bg. Tag up @ 5676'. SIP: 0. Test 5-1/2 csg to 500# for 20 min. Held good. Clean out cmt 5676-5686, drl CIBP 5686-5689. Bit plugging from scale. Circ. clean. TOH. SION. SIP: 0. TIH w/CIBP and 2-3/8" tbq. CIBP set @ 6230'. Dump 2 sx cmt on CIBP 6210-6230. TOH & LD 2-2/8" working. NU wellhead. Move out service unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann Burdette TITLE Regulatory Analyst DATE 12/19/01

Type or print name Ann Burdette

Telephone No. (817)336-2751

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any:

DRINKARD 2A
BLINEBRY SE