

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K-5098

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Hanson Oil Company	8. Farm or Lease Name Allied State
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER J, 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 18-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat B-K Queen, East
15. Elevation (Show whether DF, RT, GR, etc.) 4031' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-5/8" set @ 254' Perforations @ 4564-4607'
Top of Salt @ 1933'
5-1/2" casing shot off at 800'
P.B.T.D. @ 4638'

3-4-70 The captioned hole was filled with heavy mud and plugged and abandoned as follows:

1. A 40 sx. cement plug was set @ 4288-4638'.
2. The 5-1/2" casing was shot off and pulled @ 800'.
3. A 25 sx. cement plug was set in-and-out of the 5-1/2" casing @ 691-757'.
4. A 25 sx. cement plug was set in-and-out of the 8-5/8" casing @ 213-297'.
5. A 10 sx. cement plug was set at the surface @ 0-33' and a regulation dry hole marker erected.
6. The location was cleaned up and pits covered.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Henry F. Schuman</u>	TITLE <u>Exec. Vice President</u>	DATE <u>3-4-70</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>Jul 15 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		