

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5098

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Hanson Oil Company	8. Farm or Lease Name Allied State
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER J 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 18-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat E-K Queen, East
15. Elevation (Show whether DF, RT, GR, etc.) 4031' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-7-69 Commence drilling @ 10:00 AM with cable tools.
- 11-13-69 T.D. 256' red beds.
Ran 8-5/8" @ 254' w/150 sx. Cement circulated to surf.
- 11-14-69 WOC 24 hrs. Bailed hole dry and drilled out cement.
Tested hole 1 hour with no fillup. Rig down cable tool.
- 11-19-69 T.D. 256' red beds.
Rig up rotary and commence drilling @ 8:00 PM.
- 12- 1-69 T.D. 4946' dolomite.
Ran 5-1/2", 15-1/2#, J-55 @ 4944' w/250 sx. Incor + 5# salt per sx. WOC. Casing held 1200 psi for 12 hrs. with no leaks.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Henry F. Abraham* TITLE Exec. Vice President DATE 12-8-69

APPROVED BY *Joe E. James* TITLE SUPERVISOR DIST DATE _____

CONDITIONS OF APPROVAL, IF ANY: