N= MEXICO OIL CONSERVATION COMMISSON

SOUTHEAST NEW MEXICO PACKER LEAKAGE TEST

Operator Shell 011 Company			State B		ell (0. 6
Location Unit of Well C	Sec 33	Twp 18-S	Rge 38 -E	County	
	Reservoir or Pool	Type of Pro (Oil or Gas	d Method of Prod	Prod. Medium (Tbg or Csg)	Choke Siz
Upper Compl Hobbs Blin	ebry	011	Art Lift		None
Lower Compl Hobbs Drin	kard	011	Flow		24/64
		FLOW TEX	ST NO. 1	<u> </u>	24/04
Both zones shut-in	at (hour, date):	9-11-70	- 10:00 A.M.		
Well opened at (ho	our, date):	9-12-70	- 10:00 A.M.	Uppe r Completion	Lowe r Completi
Indicate by (X)	the zone producing.	• • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •		X
Pressure at beginn	ing of test	• • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	45	90
Stabilized? (Yes o	r No)	••••••	•••••••••	····· <u>yes</u>	ves
Maximum pressure d	uring test	••••••		60	90
	uring test				
	sion of test				
	ring test (Maximum				
	e an increase or a		Total Ti	me On	Constant
Oil Production	ur, date): <u>9-18-70</u> bbls; Grav <u>37.</u>	Gas Pr	oduction	on 168 hours	
				_	046
		4 FF 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Adam I Tr O Ham.		
				" - Per telephon	
conversation 9-18-	70 between Ray Dill owed through-out te	on and Joe Ra	mey of NMOCC. Thi		
conversation 9-18- use. (Drinkard fl	70 between Ray Dill owed through-out te	on and Joe Rast) FLOW TEST	no. 2	s test was alrig Upper	Lower
conversation 9-18- use. (Drinkard flow Well opened at (how	70 between Ray Dill owed through-out te	on and Joe Rast) FLOW TEST -70 - 1:45 P.	NO. 2	s test was alrig Upper Completion	Lower
conversation 9-18- use. (Drinkard flow Well opened at (how Indicate by (X)	70 between Ray Dill owed through-out te ur, date): 9-15	on and Joe Rast) FLOW TEST -70 - 1:45 P.	M.	upper Completion	Lower Completio
conversation 9-18- use. (Drinkard flow Well opened at (how Indicate by (X) Pressure at beginning	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ting of test	st) FLOW TEST -70 - 1:45 P.	M.	Upper Completion X	Lower Completio
conversation 9-18- use. (Drinkard flow Well opened at (how Indicate by (X) Pressure at beginning Stabilized? (Yes or	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	on and Joe Rast) FLOW TEST -70 - 1:45 P.	NO. 2	Upper Completion X 40 yes	Lower Completio
conversation 9-18- use. (Drinkard flow Well opened at (how Indicate by (X) Pressure at beginning Stabilized? (Yes or Maximum pressure du	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	on and Joe Rast) FLOW TEST -70 - 1:45 P.	M.	Upper Completion X 40 yes 60	Lower Completio
conversation 9-18- use. (Drinkard flat Well opened at (hou Indicate by (X) Pressure at beginning Stabilized? (Yes or Maximum pressure du Linimum pressure du	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	st) FLOW TEST -70 - 1:45 P.	M.	Upper Completion X 40 yes 60 32	Lower Completio
conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginni Stabilized? (Yes or Maximum pressure du Inimum pressure du Pressure at conclus	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	st) FLOW TEST -70 - 1:45 P.	M.	Upper Completion X 40 yes 60 32	Lower Completio
conversation 9-18- use. (Drinkard flow Well opened at (how Indicate by (X) Pressure at beginning Stabilized? (Yes or Maximum pressure du Pressure at conclus Pressure at conclus Pressure change dur	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	st) FLOW TEST -70 - 1:45 P.	M.	Upper Completion X 40 yes 60 32 32 28	Lower Completion 90 yes 90 90 0
conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginni Stabilized? (Yes or Maximum pressure du Pressure at conclus Pressure change dur Tas pressure change Tell closed at (hou	70 between Ray Dill owed through-out te ar, date): 9-15 Out the zone producing ing of test	rest) FLOW TEST	Total time Production	Upper Completion X 40 yes 60 32 32 28	Lower Completion 90 yes 90 90 0 Constant
conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginni Stabilized? (Yes or Maximum pressure du Pressure at conclus Pressure change dur Tas pressure change Tell closed at (hou il Production	70 between Ray Dill owed through-out te ur, date): 9-15 1) the zone producing ing of test	rest) FLOW TEST FLOW TEST -70 - 1:45 P. g. minus Minimum lecrease? Cas Prod	Total time Production	Upper Completion X 40 yes 60 32 32 28 Decrease on 48 hours	Lower Completion 90 yes 90 90 0 Constant
Conversation 9-18- use. (Drinkard flow Well opened at (hou Endicate by (X) Pressure at beginning Stabilized? (Yes or Maximum pressure du Fressure at conclus Fressure change dur Tas pressure change ell closed at (hou il Production uring Test: 25	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	rest) FLOW TEST FLOW TEST -70 - 1:45 P. g. minus Minimum lecrease? Cas Prod	Total time Production	Upper Completion X 40 yes 60 32 32 28 Decrease on 48 hours	Lower Completion 90 yes 90 90 0 Constant
conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginning Stabilized? (Yes or Laximum pressure du Cressure at conclus Pressure at conclus Pressure change dur Las pressure change ell closed at (hou il Production uring Test: 25 emarks	70 between Ray Dill owed through-out te ar, date): 9-15 1 the zone producing ing of test	FLOW TEST FLOW TEST -70 - 1:45 P. Gas Process Cas Process During Test	Total time Production Cest 43	Upper Completion X 40 yes 60 32 32 28 Decrease on 48 hours MCF; GOR_1,720	Lower Completion 90 yes 90 90 Constant
conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginni Stabilized? (Yes or Maximum pressure du Fressure at conclus Pressure at conclus Pressure change dur Tas pressure change Tell closed at (hou il Production uring Test: 25 emarks	70 between Ray Dill owed through-out te ur, date): 9-15) the zone producing ing of test	FLOW TEST FLOW TEST -70 - 1:45 P. Gas Prod Cas Prod	Total time Production lest 43	Upper Completion X 40 yes 60 32 32 28 MCF; GOR 1,720 mplete to the bes	Lower Completion 90 yes 90 90 0 Constant
conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginning Stabilized? (Yes or Maximum pressure du Pressure at concluse Pressure change dur Mas pressure change dur Mas pressure change Well closed at (hou il Production uring Test: 25 emarks hereby certify the mowledge.	70 between Ray Dill owed through-out te ar, date): 9-15 1 the zone producing ing of test	FLOW TEST FLOW TEST -70 - 1:45 P. Gas Process During Test herein contain	Total time Production luction lest 43 ned is true and co Operator She	Upper Completion X 40 yes 60 32 32 28 Decrease on 48 hours MCF; GOR 1,720 mplete to the best	Lower Completion 90 yes 90 90 Constant
conversation 9-18- ise. (Drinkard flage). (Drinkard flage). (Prinkard flage) indicate by (X) ressure at beginning tabilized? (Yes or aximum pressure during messure during tessure change during tessure change during tessure change ell closed at (housil Production during test: 25 emarks hereby certify the nowledge. Deproved SEP 29 New Mexico Oil Constitution of the production during test: 25 Deproved SEP 29 New Mexico Oil Constitution of the production of the production during test: 25 Deproved SEP 29 New Mexico Oil Constitution of the production of the produc	70 between Ray Dill owed through-out te ur, date): 9-15 1) the zone producing ing of test	FLOW TEST FLOW TEST -70 - 1:45 P. Gas Process During Test herein contain	Total time Production lest 43	Upper Completion X 40 yes 60 32 32 28 MCF; GOR 1,720 mplete to the bes	Lower Completion 90 yes 90 90 Constant
Conversation 9-18- use. (Drinkard flag Well opened at (hou Indicate by (X) Pressure at beginni Stabilized? (Yes or Maximum pressure du Pressure at conclus Pressure at conclus Pressure change dur Tas pressure change Tas press	70 between Ray Dill owed through-out te ur, date): 9-15 1 the zone producing ing of test	FLOW TEST FLOW TEST -70 - 1:45 P. Gas Process During Test herein contain	Total time Production luction lest 43 ned is true and co Operator She	Upper Completion X 40 yes 60 32 32 28 MCF; GOR 1,720 mplete to the bes 11 0il Company S. G. S ions Engineer	Lower Completio 90 yes 90 90 Constant

SOUTHEAST NEW MEXICO PACKER LEAKAGE ST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on the multiply completed well within seven days after actual completion on the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized and for a minimum of two hours thereafter, provided however, that they need not remain shut-in more than 24 hours.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued until the flowing wellhead pressure has become stabilized and for a minimum of two hours thereafter, provided however, that the flow test need not continue for more than 24 hours.

- 5. Following comple* on of Flow Test No. 1, the well shall again be shutin, in accordance w Paragraph 3 above.
- 6. Flow Test No. 2 \ge 11 be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall remain shut-in while the previously shut-in zone is produced.
- 7. All pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges, the accuracy of which must be checked with a deadweight tester at least twice, once at the beginning and once at the end, of each flow test.
- 8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the appropriate District Office of the New Mexico Oil Conservation Commission on Southeast New Mexico Packer Leakage Test form Revised 11-1-58, together with the original pressure recording gauge charts with all the deadweight pressures which were taken indicated thereon. In lieu of filing the aforesaid charts, the operator may construct a pressure versus time curve for each zone of each test, indicating thereon all pressure changes which may be reflected by the gauge charts as well as all deadweight pressure readings which were taken. If the pressure curve is submitted, the original chart must be permanently filed in the operator's office. Form C-116 shall also accompany the Packer Leakage Test Form when the test period coincides with a gas-oil ratio test period.

	CONSERVATION CALLAND
	OU CONSERVATION AND THE
	H9D(s) pt