	0 87501		Form C-103 Revised 10-1-
/.5.0.8.		State X	e of Lesse Fre
AND OFFICE -		5. Stole Cli 6 G A-1573	
SUNDRY NOTICES AND REPORTS ON WELLS	TFERENT RESERVOIR.		<u>IIIIIIII</u>
	· · · ·	7, Linit Agreeme	nt Hone
Amoco Production Company		8. Farm or Leas	
P. O. Box 68, Hobbs, New Mexico 88240	- <u> </u>	9. Well No.	
F 1980 North	1650	10. Field and Po	•
West LINE, SECTION 33 TOWNSHIP 18-S		Hobbs D	rinkard
TOWHSHIP RANG		мем. 12. County	
3660' RDB		Lea	
Check Appropriate Box To Indicate Nature of NOTICE OF INTENTION TO:		Other Data	
ALTER CASING	DRILLING OPHS.	PLUG	RING CASING
р	Completion	work	
cribe Proposed or Completed Operations (Clearly state all pertinent details, and giv J SEZ RULE 1103.	e pertinent dates, inclu	ding estimated date of	starting any propos
Ram Gamma Ray and CCL log 6992'-5700'. Spotted 2 6820'-22', 6824'-34', 6850'-60', 6870'-78', 6890'- with a 2-1/2" casing gun with 2 SPF. Ran 1 jt 2-7 nipple, and 2-7/8" tubing. Packer set at 5713' a Ray Temperature survey and pumped 12,000 gal 60% f sealers. Flush with 52 bbl N2. Ran after treatme recovered 111 BLW and 10 BO. Ran swab for 6 hrs a with 50 BFW 2% KCL. Released packer and POH. Ran casing with 90 bbl fresh water 2% KCL. Perfed 660 6636'-40', 6650'-70', 6684'-6700', 6718'-20', 6724 casing gun with 4 JSPF and 180° phasing. Ran seat 2-7/8" tubing. Packer set at 5710'. Made 6 swab and acidized with 10,000 gals of 20% HCL with addit Opened well to tank and flowed back 214 BLW. Flow and 97 BLW. Killed well with 50 bbl 2% KCL. Rele tubing, packer and 2-3/8" tubing. Tubing landed a well to tank and flowed 53 BO and 75 BLW in 7 hrs. Installed flow line and connect well to Drinkard s O+4-NMOCD.H T-HOU, R. E. Ogden, Rm 21,150 1-F. J	94', 6898'-690 /8" tubing, 5- nd tailpipe la oamed 20% HCL nt acid survey nd recovered 2 RBP, but unab 2'-08', 6612'- '-26', 6730'-3 ing nipple, 1 runs and recov ivies and 6526 ed well for 24 ased packer an t 6537' and pa Shut-in and eparator. Flo	0', 6906'-10', 1/2" packer, 2 nded at 5745', with additives . Flowed well 7 BLW and 3 BO le to get into 16', 6620'-24' 2', and 6740'- jt 2-7/8" tubi ered 30 BLW. 00 SCF N2. F1 hrs and recov d POH. RIH wi cker set at 57 moved out serv w tested 3 day	and 6918'-3 -7/8" seating Ran Gamma and 140 bal for 9 hrs an liner. Load to 626'-28', 70' with 2-1, ng, packer an Ran base log ush with N2. ered 59 BO an th 2-1/16" 49'. Opened ice unit 8-20
6820'-22', 6824'-34', 6850'-60', 6870'-78', 6890'- with a 2-1/2" casing gun with 2 SPF. Ran 1 jt 2-7 nipple, and 2-7/8" tubing. Packer set at 5713' a Ray Temperature survey and pumped 12,000 gal 60% f sealers. Flush with 52 bbl N2. Ran after treatme recovered 111 BLW and 10 BO. Ran swab for 6 hrs a with 50 BFW 2% KCL. Released packer and POH. Ran casing with 90 bbl fresh water 2% KCL. Perfed 660 6636'-40', 6650'-70', 6684'-6700', 6718'-20', 6724 casing gun with 4 JSPF and 180° phasing. Ran seat 2-7/8" tubing. Packer set at 5710'. Made 6 swab and acidized with 10,000 gals of 20% HCL with oddit Opened well to tank and flowed back 214 BLW. Flow and 97 BLW. Killed well with 50 bbl 2% KCL. Rele tubing, packer and 2-3/8" tubing. Tubing landed a well to tank and flowed 53 BO and 75 BLW in 7 hrs. Installed flow line and connect well to Drinkard s O+4-NMOCD,H T-HOU, R. E. Ogden, Rm 21.150 1-F. J	94', 6898'-690 /8" tubing, 5- nd tailpipe la oamed 20% HCL nt acid survey nd recovered 2 RBP, but unab 2'-08', 6612'- '-26', 6730'-3 ing nipple, 1 runs and recov ivies and 6526 ed well for 24 ased packer an t 6537' and pa Shut-in and <u>eparator. Flo</u> .Nash, HOU Rm	0', 6906'-10', 1/2" packer, 2 nded at 5745', with additives . Flowed well 7 BLW and 3 BO le to get into 16', 6620'-24' 2', and 6740'- jt 2-7/8" tubi ered 30 BLW. 00 SCF N2. F1 hrs and recov d POH. RIH wi cker set at 57 moved out serv w tested 3 day	and 6918'-3 -7/8" seatin Ran Gamma and 140 bal for 9 hrs a Load tubi liner. Loa , 6626'-28', 70' with 2-1 ng, packer a Ran base log ush with N2. ered 59 BO a th 2-1/16" 49'. Opened ice unit 8-2
6820'-22', 6824'-34', 6850'-60', 6870'-78', 6890'- with a 2-1/2" casing gun with 2 SPF. Ran 1 jt 2-7 nipple, and 2-7/8" tubing. Packer set at 5713' a Ray Temperature survey and pumped 12,000 gal 60% f sealers. Flush with 52 bbl N2. Ran after treatme recovered 111 BLW and 10 BO. Ran swab for 6 hrs a with 50 BFW 2% KCL. Released packer and POH. Ran casing with 90 bbl fresh water 2% KCL. Perfed 660 6636'-40', 6650'-70', 6684'-6700', 6718'-20', 6724 casing gun with 4 JSPF and 180° phasing. Ran seat 2-7/8" tubing. Packer set at 5710'. Made 6 swab and acidized with 10,000 gals of 20% HCL with oddit Opened well to tank and flowed back 214 BLW. Flow and 97 BLW. Killed well with 50 bbl 2% KCL. Rele tubing, packer and 2-3/8" tubing. Tubing landed a well to tank and flowed 53 BO and 75 BLW in 7 hrs. Installed flow line and connect well to Drinkard s O+4-NMOCD,H I-HOU, R. E. Ogden, Rm 21.150 1-F. J	94', 6898'-690 /8" tubing, 5- nd tailpipe la oamed 20% HCL nt acid survey nd recovered 2 RBP, but unab 2'-08', 6612'- '-26', 6730'-3 ing nipple, 1 runs and recov ivies and 6526 ed well for 24 ased packer an t 6537' and pa Shut-in and <u>eparator. Flo</u> .Nash, HOU Rm	0', 6906'-10', 1/2" packer, 2 nded at 5745', with additives . Flowed well 7 BLW and 3 BO le to get into 16', 6620'-24' 2', and 6740'- jt 2-7/8" tubi ered 30 BLW. 00 SCF N2. Fl hrs and recov d POH. RIH wi cker set at 57 moved out serv w tested 3 day 4.206 1-CMH	and 6918'-3 -7/8" seating Ran Gamma and 140 bal for 9 hrs an Load tubin liner. Load , 6626'-28', 70' with 2-1, ng, packer an Ran base log ush with N2. ered 59 BO an th 2-1/16" 49'. Opened ice unit 8-20

hours recovered 30 BO, 64 ..., and 37 MCF. Shut-in to run build-up and BHP tests. Flow tested 12 days and recovered 88 BO, 209 BW, and 194 MCF. Last 24 hrs flowed 0 BO, 10 BW and 10 MCF. Shut-in and POH. Ran 2-1/16" seating nipple, 2-1/16" tubing, tubing anchor, and 2-3/8" tubing. Ran rods and pump. Preparing to pump test.

and the second s

RECEIVED SEP 26 1983 HOBBS OFFICE