

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐	3. ADDRESS OF OPERATOR <i>Harlan Oil Company</i>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>4900' SW 1/4 SE 1/4, 330' from the South line and 2310' from the East line of Section 19, T 42 S, R 34 E. NMPM, Lea County, New Mexico.</i>	8. FARM OR LEASE NAME <i>Pennzoil Federal</i>
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, CR, etc.)	9. WELL NO. <i>1</i>
		10. FIELD AND POOL, OR WILDCAT <i>E K Yates - S R - Queen</i>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>19 - T18S - R34E</i>
		12. COUNTY OR PARISH <i>Lea</i>
		13. STATE <i>N.M.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) *Plug & abandon*

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT* ☒

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

April 3 - Pumped down 100' plug through tubing, 4702'. April 5th - Tagged top of cement at 2638', with tubing. (Witnessed by Mr. Goshaw of the U.S.G.S.) Loaded hole with heavy mud. April 6th, Ran 100' cement plug at 3200' to 3307'. April 10th & 11th shot 5 1/2" at 2925', 2900' and at 2701', pipe still not free. April 27th, Shot 5 1/2" casing at 2385' and 2190', worked casing free and pulled 10 joints. May 7th, ran tubing and pumped 100' cement plug at 2205'-2105', pulled balance of casing. May 10th, Ran tubing to 1709' ~~textured~~ and pumped down 100' plug 1709' to 1609'. Pumped 100' plug through tubing to 304'. May 11th, set regulation marker with 10 sacks cement surface plug. Cleaned location of all debris. Pad and road will be ripped up and relevelled as soon as the construction company can get to us.

P. And 5-11-74

18. I hereby certify that the foregoing is true and correct

SIGNED

Alvin Gaudsen

TITLE

Agent

DATE

June 25, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.