

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-23775	30-025-09932
5. Indicate Type of Lease FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS))		7. Lease Name or Unit Agreement Name NORTH HOBBS UNIT SECTION 27
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other INJECTOR		8. Well No. 111
2. Name of Operator SHELL WESTERN E&P INC.		9. Pool name or Wildcat HOBBS (G/SA)
3. Address of Operator P. O. BOX 1950, HOBBS, NM 88240 505/393-0325		
4. Well Location Unit Letter <u>D</u> : <u>1200</u> Feet From The <u>NORTH</u> Line and <u>470</u> Feet From The <u>WEST</u> Line Section <u>27</u> Township <u>18-S</u> Range <u>38-E</u> NMPM LEA County		
10. Elevation (Show whether DF, RKB, RT GR, etc) 3641' DF		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Adjust Injection Profile</u> <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09/10/96 - 09/18/96

POH W/INJ EQUIPMENT. SET CIBP @ 4100' AND CAP W/35' CMT. TEST CSG TO 500 PSI FOR 30 MIN AND CHART FOR THE NMOC. CIRC CSG W/INHIBITED FLUID. SECURE WELL FOR TA STATUS.

PURSUANT TO THE PROVISIONS OF NMOC RULE 203. SHELL WESTERN HEREBY REQUESTS TEMPORARY ABANDONMENT APPROVAL FOR A PERIOD OF FIVE YEARS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>C. L. Mann</u>	TITLE <u>PRODUCTION FOREMAN</u>	DATE <u>09/03/96</u>
TYPE OR PRINT NAME <u>C. L. MANN</u>	TELEPHONE NO. <u>505/393/1425</u>	

(This space for State Use)

APPROVED BY <u>JERRY SEXTON</u>	TITLE <u>SUPERVISOR</u>	DATE <u>SEP 06 1996</u>
CONDITIONS OF APPROVAL IF ANY:		