		_	
Submit 3 Copies to Appropriate Energy, District Office	State of New Me Minerals and Natural Re		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL (CONSERVATIO P.O. Box 208		WELL API NO.
	anta Fe, New Mexico		30-025-23'/75 5. Indicate Type of Lease
DISTRICT III			STATE FEE X
1000 Rio Brazos Rd., Aziec, NM 87410		. •	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL	OTHER INJE	CTOR .	N. HOBBS (G/SA) UNIT SECTION 27
2. Name of Operator			8. Well No.
SHELL WESTERN E&P INC.			9. Pool name or Wildcat
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)			HOBBS (G/SA)
4. Well Location			
Unit Letter D: 1200 Feet Fr	om The NORTH	Line and 47	O Feet From The WEST Line
Section 27 Towns			NMPM LEA County
	10. Elevation (Show whether I	OF, RKB, KI, GR, Ac.)	
11. Check Appropri	ate Box to Indicate N	Nature of Notice, Re	port, or Other Data
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG	S AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON 🔀 CHAI	NGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEI	MENT JOB
OTHER:		OTHER:	
 Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103. 	state all pertinent details, and	d give pertinent dates, includ	ing estimated date of starting any proposed
1. CO to 4150' (PBTD			
2. Set CIBP @ 4140' &	cap w/35' cm	nt.	
3. Pres tst csg to 500	⊭ ,		

4. Circ inhib wtr & TA well.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR APPROVED BY	_ TITLE	MAY 1 5 1989
TYPEORPRINTNAME J. H. SMITHERMAN	(713) 870-3797	TELEPHONE NO.
SIGNATURE A Amutheman	THE PROD. ADMIN. ADVISOR	_ DATE _5-4-89
I hereby certify that the information above is true and complete to the best of my knowled		