

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. <i>B-15-20</i>
7. Unit Agreement Name
8. Farm or Lease Name <i>North Vac also Unit</i>
9. Well No. <i>147</i>
10. Field and Pool, or Wildcat <i>North Vac - also</i>
12. County <i>Lea</i>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <i>WIW</i>
2. Name of Operator <i>Mobil Oil Corporation</i>
3. Address of Operator <i>Box 633, Midland, Texas 79701</i>
4. Location of Well UNIT LETTER <i>F</i> <i>2180</i> FEET FROM THE <i>North</i> LINE AND <i>1880</i> FEET FROM THE <i>West</i> LINE, SECTION <i>13</i> TOWNSHIP <i>17-2</i> RANGE <i>34-E</i> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <i>4017 GR</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Consent to a dual also and Middle Penn Injector
Spent 200 gals of 15% nov. emulsion, HCl acid from approx. 10,400' to 10,500' and perforate the following intervals in the Middle Penn formation with one jet shot per ft. 10,443, 10,445, 10,447, 10,449, 10,454, 10,456, 10,458, 10,460, 10,462, 10,464, 10,466, 10,468, 250A-12 holes. Set packer at approx. 10,400. Test Middle Penn perforation (10,442-10,469-27' OA-26 holes) down 2" tubing with 1000 gals, 5000 gals 15%. Perforate the following intervals in the also formation with 1 jet shot per ft. 8511, 8513, 8519, 8521, 8541, 8542, 8543, 8548, 8549, 8550, 8551, 8552, 41' OA-12 holes. Test also perf. (8503-8554-51' OA-31 holes). acidize also perf. (8503-8554-51' OA-31 holes) with 5000 gals 15%.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Christine O. Tucker*

TITLE *Peroration Clerk*

DATE *7-8-74*

APPROVED BY

Orig. S.
To

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: