STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION HODBS DISTRICT OFFICE

BRUCE KING GOVERNOR LARRY KEHOE

July 30, 1980

POST OFFICE BOX 1980 HORBS, NEW MEXICO 83240 (505) 393-6161

Mr. Gordon G. Marcum Pontotoc Oil Corporation P.O. Box 5094 Midland, Texas 79701

SUBJECT: Wells Suspected of Being Inadequately Cemented

Hobbs State #1, Unit F, Section 29, T18S, R38E Hobbs State #2, Unit G, Section 29, T18S, R38E

Dear Mr. Marcum:

After examining the cement bond log on your Hobbs State #1-F in Sec. 29, T18S, R38E, and the cement and casing records on the Hobbs State #2, it is agreed that additional cementing work \underline{will} not be required at this time.

At a later date some additional cementing on the above wells may have to be done since about 30 feet of formation below the intermediate casing shoe in the Hobbs State #1 is not cemented, but the casing in the well will prevent any migration of fluids out of zone.

Yours very truly,

OIL CONSERVATION DIVISION

Jerry Sexton Supervisor, District I

cc: Shell Oil Company - Attn: Bob Phillips

Mr. J.D. Ramey

Mr. Prentiss Childs