BRIDGES STATE #158

- 3/13 (13) 4129 ND lm, 124" hole, fishing past 24 hrs, Br Wtr & Oil. finish running 124" bit to 3802, top of fish, circ 1 hr, POH, ran 10-3/4 wallhook to 3802, pulled fish into center of hole, POH w/ wallhook, ran 10-5/8 OS w/ 84" grapples to 3802, caught fish, grapples slipped off fish, POH w/ OS, rerun w/ extension, caught fish, jarred on fish 2 hrs w/ no success, Dia-Log now running free pt indicator.
- 3/15 (15) 4129 ND lm, 12½" hole, fishing past 48 hrs, Br Wtr & Oil. while attempting to run free pt indicator OS slipped off fish, POH w/ OS, change slips in OS, rerun to 3802, caught fish, slipped off fish, POH, change slips, rerun caught fish, Dia-Log backed off one 8½" DC, pulled fish to 3224, stuck fish, worked and jarred on fish past 9½ hrs, spotted 50 bbls oil @ 3224.

BRIDGES STATE #158

- (16) 4129 ND lm, 124" hole, fishing past 24 hrs, Br Wtr & Oil. jarred on fish 3 hrs, bumped fish loose going down, pulled fish back to 3224, jarred 4 hrs w/ no success, bumped fish loose going down, pulled fish back to 3224, Dia-Log attempted to run outside string shot, stopped @ 1440, bumped fish loose going down, ran fish back down 3831, screwed into DC's, rel OS from fish, POH, now prep to run key seat wiper.
- BRIDGES STATE #158

  (17) 4129 ND lm, 12%" hole, fishing past 24 hrs, 10.0-40-6.8.

  ran 12% bit, reamer, DC's, key seat wiper, reamed and worked

from 3242 to top of fish @ 3802/3½ hrs, circ and cond mud 10-3/4 hrs, POH w/ bit, now GIH w/ 10-5/8 OS, WO cavings @ 3787.

BRIDGES STATE #158

- 3/18

  (18) 4129 ND lm, 12½" hole, fishing past 24 hrs, finish WO caving to top of fish @ 3802, caught fish w/ 10-5/8 OS, Dia-Log attempted to run string shot, DC's plugged, ran clean out tool, CO DC's, ran free pt indicator, indicated fish stuck @ OS, attempted to rel OS, backed off @ top of OS, POH, ran l jt 11-3/4 WP, WO fish to 3820, cont to WO fish.

  10.0-44-10.0, 8% oil.
  - 3/19

    (19) 4129 ND lm, 12½" hole, fishing past 24 hrs. 10.0-44-10.0.

    WO fish to 3822, POH w/ WP, ran DC's, attempted to screw into fish @ 3797 w/ no success, POH, ran 10-5/8 OS w/ 7-3/8 grapples, caught fish, Dia-Log attempted to run free pt indicator, DC's plugged, Dia-Log now running clean out tool.

BRIDGES STATE #158

(20) 4129 ND lm, 12½" hole, fishing past 24 hrs.

Dia-Log CO top collar, ran string shot, attempted to BO top
DC, OS slipped off fish, POH, ran screw in sub w/ guide,
screwed into fish @ 3802, Dia-Log ran string shot, attempted
to BO DC, backed off @ screw in sub, screwed back into fish
w/ sub, Dia-Log ran free pt, lost tools in DC's, fishing for
tools past 7 hrs.

10.0-43-10.0, 8% oil.