3/22

(22) 4129 ND 1m, 12k" hole, fishing past 48 hrs.
Dia-Log fished out tools, then ran SS, BO top DC 9 3813,
corrected top of fish, POH w/ OS & DC, ran screw in sub,
failed to screw into fish, POH w/ sub, ran 12k bit, CO to
top of fish 0 3813, circ 1 hr, POH w/ bit, ran 10-5/8 OS w/
7-3/4 grapples to 3813, failed to catch fish, POH, rerun OS
w/ 8" grapples, failed to catch fish, POH, ran screw in sub
w/ guide, attempted to screw into fish w/ no success, rerun
OS w/ 8" grapples, failed to catch fish, now POH w/ OS.
10.0-44-10.0, 8% oil.

## BRIDGES STATE #158

3/23 (23) 4129 ND 1m 12½" hole, fishing past 24 hrs. 10.0-48-8.0 8% 0il. Finish POH w/ overshot, no rec, ran screw in sub to 3813, failed to screw into fish, POH, rerun sub w/ kick sub to 3813, failed to screw into fish, POH, ran 10-5/8" overshot, failed to catch fish, POH, rec 8' sliver off DC, ran screw in sub, failed to screw into fish, ran overshot w/ mill guide, milled over fish 2 ft., failed to catch fish, POH, prep to run mill on short piece of wash pipe.

## BRIDGES STATE #158

3/24 (24) 4129 ND 1m, 12-1/4" hole. Fishing past 24 hrs. 10.0-48-8.0 8% 0il. Top of fish 3813, ran washover shoe, washed over top of fish 4', POH, ran 10-5/8" overshot. Attempted to catch fish w/no success, POH w/overshot, ran screw-in sub. Failed to screw in, POH, reran screw-in sub w/kick sub. failed to screw in, reran overshot, failed to catch fish, POH. Ran 11-3/4" O.D. overshot w/8-3/4" grapples. Now attempting to catch fish.

#### BRIDGES STATE #158

3/25

(25) 4129 ND 1m, 12-1/4" hole. Fishing past 24 hrs. 10.0-50-7.0 5% 0il Top of fish 3839', attempted to catch fish @ 3813' w/11-3/4" overshot & 8-3/4" grapples w/no success, POH, reran overshot w/ 8-1/4" grapples. Caught fish, jarred on fish 1-1/2 hrs, then ran Dia-log, backed off top DC w/string shot, POH. Rec. 1 DC, ran 12-1/4" bit, CO to top of fish 3839'. Cond hole 3-3/4 hrs, POH w/bit, ran 9 jts wash pipe. Prep to wash over fish.

# BRIDGES STATE #158

3/26 (26) 4129 ND 1m, 12-1/4" hole, fishing past
24 hrs. Top of fish 3839. Washed over fish to
3881 in 10-3/4 hrs. POH, ran new mill, milled
@ 3881 past 7-3/4 hrs.

10.0-45-6.0 6% 0i1.

#### BRIDGES STATE #158

3/27

(27) 4129, prep to drill 12½" hole, 10.0-43-8.0, 6% oil.

Attempted to washover fish 3 3881/4 hrs - no success, POH w/ WP, ran jars, DC's and accelerator sub, screwed into fish 6 3839, jarred fish loose in 8 hrs, POH w/ fish, rec 10 DC's, left one cone off bit + sinker bars off Dia-Log equip in hole, prep to drill.