		•
HO. OF COPIES RECE	IVED	Form C-103
DISTRIBUTIO		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		Ellective 1-1-03
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
	,	E-1482
-	SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE	THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.	GAS OTHER-	7, Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
TEXACO Inc	•	New Mexico 'DH' St.
3. Address of Operato		9. Well No.
P. O. Box	728, Hobbs, New Mexico 88240	ן ז_ע
4. Location of Well		10. Field and Pool, or Wildcat
	A , 380 FEET FROM THE North LINE AND 330 FEET FROM	Totale Dellarene
UNIT LETTER	A , 300 FEET FROM THE HOT UT LINE AND 330 FEET FROM	LUSK DETAWATE
Fost	30 10-9 3 9- F	
THE <u>East</u>	LINE, SECTION 32 TOWNSHIP 19-S RANGE 32-E NMPM.	
riminini	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3551 GR	
16.		Lea
ŀ	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
PERFORM REMEDIAL W		ALTERING CASING
TEMPORARILY ABANDON		PLUG AND ABANDONMENT
PULL OR ALTER CASING		
6	OTHER	
OTHER		
work) SEE RULE		
1.	Ran CIBP and set @ 4742, dumped 3 sacks cement behale 1/9.5# mud.	1742-4707. Displaced
2.	Shot and pulled $5\frac{1}{2}$ casing.	
3.	Ran CIBP and set in 7 5/8" casing @ 2700, dumped from 2700-2665.	i 10 sacks cement
£ 4.	Spotted 10 sacks cement @ surface.	
5.	Installed dry hole maker and cleaned location.	
	Subject well plugged and abandoned 8724-73.	,

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED APPROVED BY