

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>32-225-23765</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 18
8. Well No. 341
9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> INJECTOR
2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 5237)
4. Well Location Unit Letter <u>0</u> : <u>580</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>18</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3672' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TA'd ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-16 to 3-24-94:

Attmpd to rel inj pkr, could not. Chkd well file & noted crooked hole in 5-1/2" csg btw 2475' & 2492'. Attmpd to get thru ti spot @ 2492' w/1-7/16" colr locator & free point tool, could not. Attmpd to get thru ti spot 2475-92' w/1" spud bars. Was successful twice, but was unable to go thru ti spot 3rd time. POH. RIH w/string shot & 3/4" colr locator. Was able to go thru ti spot. Shot string shot in colr of 2 jts abv pkr. POH w/120 jts 2-3/8" IPC tbq. Left 4 jts tbq & pkr in hole. Top of tbq @ approx 3775'. Discussed situation w/ NMOCD. RIH w/CIBP for 5-1/2" csg. Could not get below 2475', POH. RIH w/smaller dmp blr's, same results. POH. Discussed situation w/NMOCD's Jerry Sexton & engr. Agreement made to spot cmt plug abv pkr & cut off tbq. RIH w/OE tbq to 3775'. Spot 50 sx Cls "C" cmt w/2% CaCl2. WOC overnite. Tag TOC @ 3724'. Attmpd to PT csg, wouldn't hold. Pmpd 50 sx Cls "C" Neat. Tag TOC @ 3443'. Circ inhib fl. PT csg to 500#, held. (Chart attached) Secured well for TA status. Well is TA'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE A. J. DURRANI TITLE TECH. MGR. - ASSET ADMIN. DATE 4/14/94
TYPE OR PRINT NAME A. J. DURRANI (713) 544-3797 TELEPHONE NO.

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY JERRY SEXTON
DATE 4/15/94

APR 19 1994

Assignment Expires