

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ TA'd2. NAME OF OPERATOR
Sun Exploration & Production Co.3. ADDRESS OF OPERATOR
P.O. Box 1861, Midland, Tx. 797024. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit Ltr. L 1980' FSL & 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) PLUG ☒

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐5. LEASE
NM-063530
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Shearn Federal *com*9. WELL NO.
110. FIELD OR WILDCAT NAME
Lusk Delaware11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 15, T-19 R-3212. COUNTY OR PARISH: Lea 13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. Install BOP. RIH w/ 2-7/8 WS OE. Load hole w/ 9.5 PPG mud laden fluid. POH.

RIH w/ 9-5/8" CIBP on 2-7/8 WS. Set CIBP at 4950'. Spot 35' cmt plug on top of CIBP. (Approx 12 sx). POH.

RU csg jacks, locate free point of 9-5/8" csg (T0C-4100'). Cut off csg at approx 3500' ±. POH and LQ 9-5/8" csg.

RIH w/ 2-7/8 WS to top of csg stub. Spot 100' CL "C" cmt in out out of csg stub. PU tbg to 2500'±. WOC overnight, lower tbg, tag top of plug. PU tbg to 2750'.

Spot 200' CL C cmt plug from 2750'-2550', PU tbg. WOC overnight. Lower tbg, WOC Overnight. Lower tbg, tag top of plug, PU tbg to 1050'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *De Ann Kemp* TITLE Sr. Acctg. Assist. DATE 6/1/84

(This space for Federal or State office use)

APPROVED BY *R. B. Ritchie* TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY