State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		-	
DISTRICT I	OIL CONSERVATIO	N DIVISION	WELL API NO.
P.O. Boy 1980, Hobbs NM 88240 P.O. Box 2088		30-025-23988	
DISTR: T II P.O. Dr. wer DD, Artesia, NM 88210	Santa Fe, New Mexico	8/304-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B-2229
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name PHILMEX
1. Type of Well: OIL GAS WELL WELL			1
2. Name of Operator		8. Well No.	
Phillips Petroleum Company			9. Pool name or Wildcat
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762			MALJAMAR GB/SA
4. Well Location Unit Letter M : 569	Feet From The SOUTH	Line and 50	77 Feet From The WEST Line
Section 28 Township 17 S Range 33 E NMPM LEA County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
4096' GR			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
NOTICE OF INTENTION TO:		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING		GOPNS. 🔲 PLUG AND ABANDONIMENT 🛚	
PULL OR ALTER CASING CASING TEST AND C		EMENT JOB	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
4/12/95 NIRU DDU, ND WELLH4/12/05 Objective: Plug and Abandon Wellbore Notified NMOCD (C. Perrin) 4/11/95, 12:00 pm CDT on intent to P&A Well. MIRU Sierra Well Service DDU #3, RU plugging eqmt, opened well, bled of 500 psi. Well Dead. Chgd out BOPE rams. ND wellhead. NU Class 1 manual BOPE. TOH/LD 85 jts 2-7/8" salta lined tbg, left fish in hole. Tbf was parted in middle of collar. TIH W/overshot on 2-3/8" workstring, tagged/latched onto fish at 2707'.			
Rec'd approval from NMOCD (C.Perrin) to cut tbg & leave packer in hole. Pulled 50# on pkr, attempted to unset pkr, no success. Moved Pkr downhole			
appox. 50'.	ir, accempted to unset	pki, ilo success	. Hoved FRI downhole
Secured Well. SD	Secured Well. SDON. (over)		
I hereby certify that the information above is	true and complete to the best of my knowledg	ge and belief.	
SIGNATURE	anders T	TLE <u>SUPERVISOR, I</u>	REG. AFFAIRS DATE 4/20/95
TYPE OR PRINT NAMEMSANDE	RS	***	TELEPHONE NO.915/368-1488
(This space for State Use)			
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	Rolinson II	TLE	DATE

4/13/95 RU WIRELINE, RAN 1.58" SUPER JUTTER, UNABLE TO RUN CUTTER .-PAST OBSTRUCTION @ 4367'. UNABLE TO PUMP DOWN TBG OR ANNULUS @ 500 psi. NOTIFIED NMOCD (JERRY SEXTON), REC'D APPROVAL TO CUTOFF TBG & LEAVE PKR IN HOLE. CUT TBG @ 4365'. POH W/WIRELINE. WORKED PIPE PULLED PKR. POH/LD 154 JTS 2-7/8" TBG AND PKR. PU/RIH W/CIBP, SET @ 4800', SECURED WELL SDON.

HELD SAFETY MIG, OPENED WELL - DEAD, MIXED 10 PPG MUD-LADEN 4/17/95 BRINE.

SPOT PLUG #1, 25 SX CMT, 4800' - 4560',

***Note: ALL PLUGS ARE CLASS C CMT MIXED @ 14.8 PPG & $1.32 \, \text{FT/3SK}.$

PULLED UPHOLE, BOT @ 3981'.

SPOT PLUG #2, 25 SX CMT, 3981' - 3741'.

PULLED UPHOLE, BOT @ 2663'. SPOT PLUG #3, 25 SX CMT, 2663' - 2423'.

PULLED UPHOLE, BOT @ 1507'.

SPOT PLUG # 4, 25 SX CMT, 1507' - 1267'.

PULLED UPHOLE, BOT @ 412'.

SPOT PLUG #5, 50 SX CMT, 412' - SURFACE.

PULLED/LD TBG, WASHED UP/ND BOPE.

RDMO PLUGGING EQMT, WELL IS PLUGGED. RECLAMATION TO BE DONE AT A LATER DATE.

