STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

80. 0° torito acceives	T	
DISTRIBUTION		
SANTA PE		
FILE		
U.S.G.S.		
LAND OFFICE		
CPERATOR		

JIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 Revised 19-1-78

PILE .	Sa. Indicate Type of Lease
U.S.O.S.	State X Foo
LAND OFFICE OPERATOR	5. State Oil & Gas Lease No.
	B-3936-1
SUNDRY NOTICES AND DEPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS THIS FORM FOR PROPOSALS TO DRILL OR TO DEFECT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-101) FOR SUCH PROPOSALS.	
1.	7. Upit Agreement Name
OIL K GAS WELL OTHER-	7. Vacuum Grayburg
2. Name of Operator	San Andres 8. Form or Lease Name
	Vacuum Grayburg
Texaco Inc.	San Andres
	20
P. O. Box 728, Hobbs, New Mexico 88240	
4. Location of Well	10 Vacuum odrayburg
UNIT LETTER	San Andres
THE SOUTH LINE, SECTION 10 YOWNSHIP 18-S RANGE 34-E NMPM.	
,	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
(1)	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
•••	REPORT OF:
1001102 01 1111 2111 1011	
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPOPARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	
OTHER Convert to Water Injection X	
OTHER COLLY OF A ACCOUNTS TO THE STATE OF TH	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	
1. Rig up. Pull rods & pump. Check TD w/tubing.	
	ъ
3. Wash perfs. 4403'-4699' w/500 gals. 15% NE Acid. Swa	.0.
4. Pull tubing.	N k a = a .
5. Run 2 3/8" OD plastic coated tubing w/Pkr. Set pkr. @	43501.
6. Load Annulus w/inhibited water.	
7. Commence water injection.	
· ·	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
	h. 4= 40 ::
Asst. Dist. Mgr.	DATE 4/3/81
	2 1 1 A
	600 0 19 81
APPROVED BY	DATE
•	