

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-4735	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry</u></p>		7. Unit Agreement Name
<p>2. Name of Operator</p> <p><u>John H. Hill</u></p>		8. Farm or Lease Name
<p>3. Address of Operator</p> <p><u>1411 West Avenue, Suite 100, Austin, Texas 78701</u></p>		9. Well No.
<p>4. Location of Well</p> <p>UNIT LETTER <u>B</u>, <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM</p> <p>THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>18S</u> RANGE <u>34E</u> N.M.P.M.</p>		10. Field and Pool, or Wildcat
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p> <p><u>4037 G.L., 4046 K.B.</u></p>		12. County

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work to commence about 9-18-73. Perfs. 4068-4401. Will pump 15 sk cement plug down casing and spot @ 3850-4000'. Set jacks, shoot 4-1/2" casing @ approx. 3700', top of cement outside 4-1/2" @ 3780'. Spot 25 sk cement plug @ stub, pump down w/mud. Spot ⁴⁵25 sk cement plug 1850-2000', top of salt @ 1930'. Spot ⁵⁵25 sk cement plug 400-500', surface casing @ 438'. Set 10 sk cement plug @ surface w/dry hole marker. Will fill pits and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>Supt.</u>	DATE <u>9-11-73</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		