

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE
ORDER INSTRUCTIONS
7-75E (10/81)

175-
1-75

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT
2. NAME OF OPERATOR SHELL WESTERN E&P INC.	8. FARM OR LEASE NAME SECTION 30
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. WELL NO. 341
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface UNIT LTR O, 990' FSL, 1650' FEL	10. FIELD AND POOL OR WILDCAT HOBBS (G/SA)
14. PERMIT NO. API #30-025-07443	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA SEC. 30, T18S, R38E
15. ELEVATIONS (Show whether DF, KT, GR, etc.) 3655' DF	12. COUNTY OR PARISH, 13. STATE LEA NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	WELL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANT ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-16-85: Pulled production equipment.

12-17 to 12-18-85: Cleaned out to 4250'. Set a CIBP @ 4202'. Attempted to set RBP @ different depths above & below 4090'. Could not set RBP. Retrieved RBP. Set pkr @ 4048'. Pres tstd 3-1/2" liner top @ 3715' to 500#, held OK. Released pkr & re-set @ 4090'. Sqzd perf's 4056' - 4077' did not hold @ 200# pres.

12-19 to 12-20-85: POH w/pkr. PB to 4097' w/800# 8-12 mesh sand.

12-21 to 12-22-85: Re-sqzd perf's 4056' - 4077' w/75 sx Class "C" cmt +.2% Halad-4 + 2% CaCl₂ followed by 75 sx Class "C" cmt + 2% CaCl₂. WOC 24 hrs.

12-23 to 12-30-85: Tagged TOC @ 3606'. Drld out cmt to 4100'. Cleaned out sand to 4202'.

12-31-85: Ran GR/CCL log from 4108' to 4000'. Perf'd San Andres 4103' - 4128' (2 JSPF, 16 holes).

1-02-86: Add perf's 4103' - 4128' w/3200 gals 15% HCl-NEA + 450# rock salt.

1-03-86: Installed production equipment and returned well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITS DATE JANUARY 9, 1986

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: _____
ACCEPTED FOR RECORD

JAN 15 1986

*See Instructions on Reverse Side