

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. N.M. 6863
2. NAME OF OPERATOR MEWBOURNE OIL COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. BOX 5270 - HOBBS, NEW MEXICO 88241		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990/8 J W		8. FARM OR LEASE NAME ANADARKO FED.
14. PERMIT NO. 30-025-24742		9. WELL NO. 4
15. ELEVATIONS (Show whether DF, RT, OR, etc.)		10. FIELD AND POOL, OR WILDCAT Green Lake Plains Green Lake
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SOC 27 T-18S R-32E 990 FSL 990 FNL
		12. COUNTY OR PARISH LEA
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. SET 4½ CIBP AT 3830' W/3 SKS CEMENT.
2. LOAD HOLE W/MUD
3. CUT O PULL 4½ CASING FROM 2268'
4. SPOT 40 SKS CEMENT AT 2444' O WOC TAGGED PLUG AT 2265'
5. SPOT 20 SKS CEMENT AT 2265' CALCULATED TOP OF CEMENT 2218'
6. SPOT 35 SKS CEMENT AT 1327' WOC TAGGED PLUG AT 1272'
7. SPOT 25 SKS CEMENT AT 1272' WOC TAGGED PLUG AT 1120'
8. SPOT 45 SKS CEMENT AT 370' WOC TAGGED PLUG AT 304'
9. SPOT 20 SKS CEMENT AT 304'
10. SPOT 4 SKS CEMENT AT 50' TO SURFACE O SET P&A MARKER.

18. I hereby certify that the foregoing is true and correct

SIGNED

Raymond Maldonado

TITLE

P&A SUPERVISOR

DATE

7-25-91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9/27/91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side