Form 9-331

SUBMIT IN TRIPL .E. UNI D STATES

Form approved.

(May 1905)	DEPARTMENT OF THE INTERIOR (Other Instructions re						5. LEASE DESIGNATION AND SERIAL NO.		
	GEOLOGICAL SURVEY					NM 18302			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL XX GAS WELL OTHER						7. UNIT AGREEMENT NAME			
WELL AA WELL OTHER 2. NAME OF OPERATOR						8. FARM OR LEASE NAME			
PETROLEUM DEVELOPMENT CORPORATION						McKay West Federal			
3. ADDRESS OF OPERATOR						9. WELL NO.			
9720 B Candelaria, NE, Albuquerque, NM 87112 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface						10. FIELD AND POOL, OR WILDCAT Querecho Plains Bone Springs			
1980' FNL & 1980' FWL, Section 34, T18S, R32E						11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T18S, R32E			
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				PT AP eta)	12. COUNTY O		-		
14. PERMIT NO.	- 3706 GL				Lea	A TARISE	NM		
10							140.4		
16. Check Appropriate Box To Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO:						Jiner Daia UENT REPORT OF:			
				ŗ	-				
TEST WATER SHUT-C		LL OR ALTER CASING		WATER SHUT-OFF FRACTURE TREATMENT	V -	PAIRING W TERING CA	11		
SHOOT OR ACIDIZE	AE	ANDON*		SHOOTING OR ACIDIZING		ANDONMEN	T*		
REPAIR WELL	CI	IANGE PLANS		(Other) Temporary (Nore: Report results)	Abandonme	nt.	n Well		
(Other)	D COMPLETED OPEN	mione (Claudy state	all portingué	Completion or Recon	apletion Report as	nd Log for	m.)		
proposed work. Is nent to this work.)	well is direction			details, and give pertinent date	ical depths for a	l markers	and zones perti		
Summary of Work	Parformed.	COR	RECT	ED REPORT					
3/4/79 thru 4/2									
	•	5' cement on	top of	plug. Tested plug	to 2000 ps	si, he	ld.		
				80 tubing & packer,					
				ized, w/1000 gal 7½					
				show, swabbed dry. 2.75 BPM @ 2700 ps					
swabbed drv.				·			Η,		
Fracture treate	d Delaware	perfs. 4904-	4918, w	/6000 gal. gelled 4	2 ⁰ oil and	500#			
20/40 mesh sand	at 3 BPM a	t 3500 psi.	Would	not take sand. Wai	ted 18 hou	rs for	gel		
to break. Swab Pulled tubing a	bed 28 bbls nd packer.	Installed	swabbe 10" fla	d dry. SI 4 days, nge with 2" valve.	ran swab,	still (dry.		
Temporarily aba	ndoned.			- 4	Tili-10	i i i National de la companya de la compan	P-CS		
, ,				1-80					
	\$P.o.~.	il of temporal			MAY S	2 197	9		
This approval of temporary 5480 abandonment expires)GICAL *	SURVEY		
	abandos				HOBBS, N	IEW ME	XICO		
18. I hereby certify that	the foregoing is	true and correct							
SIGNED LIGHT	y & & W	tayere ,	TITLE Vi	ce President	RAFE	5/1/	79		
(This space for Fed	eral or State office	use)		ce President ACCEPTED F	OK KERAKA	<u> </u>			
APPROVED BY	PPROVAT. TO AN		TITLE	/ ACULPILD	3 1979	M-			
*See Instructions on Reverse Side, S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO									
) 2501	OGICAL SUICC	, \			
		*See	Instructions	on Reverse Side. S. GEOR	NEW MILL				
				HOBBO					

OIL CONSERVATION COMM.

 $\mathbb{P}^{4}(\mathbb{P}^{n}) = \mathbb{P}^{2}(\mathfrak{g})$

No production of the control of the

. 24**52** .