

District I
1625 N. French Dr., Hobbs, NM 87240

District II
811 South First, Artesia, NM 87210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.	30-025-25022
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	E-2439
7. Lease Name or Unit Agreement Name	Cockburn B State
8. Well No.	8
9. Pool name or Wildcat	E K Yates 7 Rvrs Qn
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ OtherTA'd

2. Name of Operator
Saga Petroleum LLC

3. Address of Operator
415 W Wall, Suite 1900
Midland, TX 79701

4. Well Location

Unit Letter G : 1980 feet from the N line and 1460 feet from the E line

Section 1 Township 18S Range 33E NMPM County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

TD 4305', PBTD 4269', Perfs 4132'-4168'

12-1/4" hole - 8-5/8" 24# @ 345', cmt w/250 sx circ.

7-7/8" hole - 5-1/2" 14 & 15.5# @ 4302', cmt w/200 sx (CBL 3030') CIBP @ 4063'.

RIH, 25 CIBP @ 4063', spot 10 sx cmt on top. M&P 9.5# mud laden fluid, POOH to 3345'

M&P 10 sx cmt plug from 3445'-3345'. M&P 9.5# mud laden fluid, POOH to 2988'.

20 sx cmt plug from 3088'-2988'. M&P 9.5# mud laden fluid, POOH to 2830'

Perf 2 sqz holes @ 2930', EIR, M&P 35 sx cmt from 2930'-2830', POOH. M&P 9.5# mud laden fluid, POOH to 2830'

Perf 2 sqz holes @ 1932', EIR, M&P 35 sx cmt from 1932'-1832', POOH. M&P 9.5# mud laden fluid, POOH to 2060'

Perf 2 sqz holes @ 395', EIR, M&P 80 sx cmt, circ cmt to surface, spot cmt in 5-1/2" csg to 295', POOH.

M&P 9.5# mud laden fluid, POOH.

M&P 10 sx cmt surface plug. ND BOP, cut off csg 3' below ground level.

Install dry hole marker, clean location & backfill workover pit

TAG ALL SHOE PLUGS + PERF HOLES

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 12/23/2002

Type or print name Bonnie Husband

Telephone No. (905)684-4293

(This space for State use)

APPROVED BY

Conditions of approval, if any:

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE 03 2003

