

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25116
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 26	
8. Well No.	311
9. Pool name or Wildcat	HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3685' DF	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Shell Western E&P Inc.
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576	4. Well Location Unit Letter B : 330 Feet From The NORTH Line and 1900 Feet From The EAST Line Section 26 Township 18S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3685' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TA'D <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-06 TO 7-07-92:

POH W/PROD EQMT. CO W/BIT & SCRPR. SET CIBP @ 4175'. PT CSG TO 540# FOR 30 MIN,
GAINED 10#. MIT WITNESSED BY NMOCD'S MR. BUDDY HILL. (CHART ATTACHED) SECURED WELL
FOR TA'D STATUS. CLN LOC. WELL TA'D.

PURSUANT TO THE PROVISIONS OF NMOCD RULE 203, SHELL WESTERN HEREBY REQUESTS TEMPORARY
ABANDONMENT STATUS FOR A PERIOD OF FIVE YEARS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Marcus Winder TITLE TECH. MANAGER - ENVIR. ENG. DATE 7/14/92
TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3797


(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 7-14-94



For TA Chart

SWEPI-NMBU
HOBBS FIELD, NMBU
MECHANICAL INTEGRITY
TEST OF INJECTION
WELL NO. 26-37
NMCD RULE 704

DATE

SWEPI REP SIGNATURE

OCD REP SIGNATURE

PUMP OPERATOR SIGNATURE

8-26-18-37
Pressured to 540#
to 350#, held to
30 MIN.
7/7/92
F. 4.11