

|              |  |  |
|--------------|--|--|
| DISTRIBUTION |  |  |
| SANTA FE     |  |  |
| FILE         |  |  |
| U.S.G.S.     |  |  |
| LAND OFFICE  |  |  |
| OPERATOR     |  |  |

P.O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-101  
Revised 10-1-78

# SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐ (RE-ENTRY)

Name of Operator  
DINERO OPERATING COMPANY

Address of Operator  
POST OFFICE DRAWER 10505, MIDLAND, TEXAS 79702

Location of Well

UNIT LETTER F, 1980 FEET FROM THE North LINE AND 1980

West LINE, SECTION 19 TOWNSHIP 18-S RANGE 35-E

15. Elevation (Show whether DF, RT, GR, etc.)  
3959. G.L.

|                              |                                                                        |
|------------------------------|------------------------------------------------------------------------|
| 1. Indicate type of lease    | State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 2. State Oil & Gas Lease No. | I-6901                                                                 |
| 3. Unit Agreement No.        |                                                                        |
| 4. Field or Lease Name       | MESA MERRITT STATE                                                     |
| 5. Well No.                  | 1                                                                      |
| 6. Field and Name of Well    | Widecat-Airstrip                                                       |
| 7. County                    | Lea                                                                    |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

NEW REMEDIAL WORK ☐  
REABLY ABANDON ☐  
OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENT ON SENSING ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

Acidizing ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give precise dates, including estimated time of starting any proposed work) SEE RULE 1103.

March 6, 1982: Acidized perms in Wolfcamp Zone 10,366' to 10,384' by Dresser Titan  
10,000 gallons of 20% Acid, 31 gallons I-11, 1 gallon NE-12, 250# LFW-30, 67 gallons  
MSS-4, 30 gallons LEA-71, 20 gallons TFS 2000

Max. pressure, 7300#

Average 6700#

Final 4600#

Total load to recover 316 barrels

Release pressure and start recovery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

*Lavanda Norman*

TITLE Production Clerk

DATE March 10, 1982

ORIGINAL SIGNED BY

JERRY SEXTON

DISTRICT 1 SUPERVISOR

DATE BY

DATE MAR 16 1982

NOTATIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 1 1967

O CD  
HOBBS OFFICE