

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-12412

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Sun Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1861, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

660' FNL & FWL of Sec. 22, T-19-S, R 32E, Unit D

14. PERMIT NO.

Blanket

15. ELEVATIONS (Show whether DF, WT, GR, etc.)

GR 3612, RDB 3633

UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sloan Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

East Lusk-Wolfcamp

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 22, T-19-S, R-32-E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1978

4-22 MI & RU, NU BOP, pull 2 7/8" tbg & pkr. Dumped 10 sks cmt on CIBP at 10035' set GO 7" CIBP at 7900', dumped 6 sks cmt on CIBP.

4-23 Crews off

4-24 RIH w/2 7/8" tbg to 7700', circ hole w/10# mud, spot 70 sk cmt plug 3700/3848, spot 35 plug 2780/2866 spot 35 sk plug 950/1080, spot 30 sk plug from 90' to surface, ND BOP & WH.

4-25 Cut off wellhead, weld on steel plate and dry hole marker. RR 10 AM.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Don Harry*

TITLE

Office Assistant

DATE

4-26-78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUL 27 1978

ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

APPROVED

RECEIVED

AUG 1 1978

COMMUNICATION COMM,  
10533, N M