

## ATTACHMENT SHEET -

37. SUMMARY OF POROUS ZONES:

<u>Formation</u>	<u>Top</u>	<u>Bottom</u>	<u>Description, Contents, Etc.</u>
Bone Spring	9938	9970	DST #4: Op. 10", ST 60", Op 90", ST 90", GTS/20", TSTM. Rev. out 7500' sli oil heavy &c drilling fluid. ISIP 3784, IFP 1174-2289, FFP 2441-3772, FSIP 3784. BHT 142°, MFE Rec. 2450 cc drig. fluid & 110,000 ppm Cl. Res. 0.14 @ 58° + .1 cf gas @ 75 psi.
" Camp	10,424	10,458	DST #5: Op 15", ST 90", Op 120" - ST 240" - GTS/8" incr. to 925 MCFPD in 15" decr. throughout 2nd flow, dropped bars, circ. valves would not open. Ran Dia-Log. perf 2 holes @ 9230' tools stuck, pulled loose. Circ. out 20 bbls. oil. Pulled out of hole. Top circ. sleeve plugged w/LGM 14th DC off bottom also plugged, pressure trapped below. Total recovery 25 BO, MFE recov. 3.6 c.f., gas at 100% 1100 CC oil 42°, API, BHT 149° F., HR 5065-5065, IF 287-313, ISI 2442, FF 287-794, FSI 1935.
Morrison	12,589	13,007	DST #6: 15"-120"-120"-360", GTS 29", 2nd flow stab. at 900 MCFPD. Recov. 200' cond. reversed out 1500', WB, 200' cond. MFE recov. 200 cc. cond. 600 cc. drig. mud 6 c.f. gas @ 1000 psi. HR 6634-6594; IFP 942-972; ISI 5974; FFP 1029-1437; FSIP 5974; BHT 177° F.

RECEIVED  
MAR 28 1976  
61 CONSERVATION COM.  
LAWRENCE, KAN.