UNITE STATES SUBMIT IN TRIPLICAT (May 1963) UNITE STATES SUBMIT IN TRIPLICAT DEPARTMENT CT THE INTERIOR (Other instructions on verse side)					Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY				06798		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) 				6. IF INDIAN,	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME	
				7. UNIT AGREE		
				8. FARM OR LE		
				9. WELL NO.	Shell Federal	
				o. willing.	1	
				10. FIELD AND	 FIELD AND FOOL, OR WILDCAT Wildcat SEC., T., R., M., OR BLK. AND SURVEY OR ABEA 	
				Wildca		
				11. SEC., T., R., SUBVEY		
					-195, R-32E NME	
4. PERMIT NO.		15. ELEVATIONS (Show whether D	F, RT, GR, etc.)			
		3666 GL	. ,,	Lea	PARISH 13. STATE	
i.	Check A.			1	New Mexic	
NOT	CHECK A	ppropriate Box To Indicate N	Nature of Notice, Report,	or Other Data		
	[····· -]		SU	BSEQUENT REPORT OF ;		
TEST WATER SHUT-OFF	l r	PULL OR ALTER CASING	WATER SHUT-OFF	REPA	AIRING WELL	
FRACTURE TREAT SHOOT OR ACIDIZE		MULTIPLE COMPLETE	FRACTURE TREATMENT		RING CASING	
REPAIR WELL	- ··· {	ABANDON*	SHOOTING OR ACIDIZING	ABAN	DONMENT*	
(Other)	1 1	CHANGE PLANS	(Other) Spud &	& Surface Cas	ing vy	
		RATIONS (Clearly state all pertinen mally drilled, give subsurface local	(NUTE: Report re: Completion or Rec	sults of multiple comp completion Report and	alotion on W-11	
			led 24" conductor l emented with 5 yard	 hole to 40 fee ds ready mix.	et.	
		o.m. 10/30/75. Dril: Conductor pipe. Co Preparing to move p		hole to 40 fea is ready mix.	et.	
				hole to 40 feads and the seady mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fea is ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fea ds ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fea ds ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
				hole to 40 fe ds ready mix.	et.	
Job complete 11	/01/75.			hole to 40 fea ds ready mix.	et.	
	/01/75.	Preparing to move of the state	emented with 5 yard in rotary rig. -	hole to 40 fea ds ready mix.	et.	
Job complete 11	topegoing is	Preparing to move of Preparing to move of Current TITLE Sec	emented with 5 yard in rotary rig. - -	ds ready mix.	et. 11/03/75	
Job complete 11 I hereby certify that the SIGNED	topegoing is for for state office	Preparing to move of Preparing to move of Current TITLE Sec Use)	emented with 5 yard in rotary rig. - -	ds ready mix.		
Job complete 11 I hereby certify that the SIGNED Thus (This space for Federal o	topegoing is for for state office	Preparing to move of Preparing to move of Mulence TITLE Sec use)	cretary ACCEPTED FOR RE	DATE 5 ORD		
Job complete 11 I hereby certify that the SIGNED	topegoing is for for state office	Preparing to move of Preparing to move of Mulence TITLE Sec use)	cretary ACCEPTED FOR RE	DATE 5 ORD		
Job complete 11 I hereby certify that the SIGNED	topegoing is for for state office	Preparing to move of Preparing to move of Mulence TITLE Sec use)	emented with 5 yard in rotary rig.	DATE 5 ORD		

.

1

-