Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240	Roy 1980 Hobbs NM 88240			WELL API NO.	
P.O. Box 2088			30-025-25167		
P.O. Drawer DD, Ariesia, NM 88210			5. Indicate Type	of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Ga	· · · · · · · · · · · · · · · · · · ·	
SUNDRY NOTIC	ES AND REPORTS ON WE	IIS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name BRIDGES STATE		
1. Type of Well:	01) FOR SUCH PROPOSALS.)		BRIDGES STA	I E	
OL GAS WELL X	OTHER.				
2. Name of Operator			8. Well No.		
Mobil Producing Tx. & N.M. Inc.*			183		
3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702			9. Pool name or Wildcat VACUUM (WOLFCAMP)		
4. Well Location					
Unit Letter B : 910	Feet From The NORTH	Line and	2055 Feet From	n The EAST Line	
Section 12		ange 34-E	NMPM LEA	County	
	10. Elevation (Show whether KB 4037	DF, RKB, RT, GR, etc.)			
11. Check At		Nature of Notice R	enort or Othe		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND C			MENT JOB		
OTHER:		OTHER:			
12. Describe Proposed or Completed Operation	ns (Clearly state all pertinent details, a	nd give pertinent dates, inclu	ding estimated date of	of starting any proposed	
work) SEE RULE 1103.					
1. MIRU PU. DIG PIT. FLOW WEL					
2. RIH W/WS TO 9900. LOAD HO 3. PUH TO 6201. SPOT 25 SX CL	DLE W/10PPG GELLED BRIN	E.	6001 6001		
4. PUH TO 4900. SPOT 50 SX CL	C PLUG ACROSS CSG SHOP	e 4850, GRAYBURG	SAN ANDRES	TOP @ 4665 & TOL @ 4655	
FROM 4900-4600.					
5. PUH TO 3010. SPOT 50 SX CL 6. PUH TO 1860. SPOT 50 SX CL	C PLUG ACROSS YATES TO	DP @ 2954 FROM 30°	10-2880. 1-1730		
7. PUH TO 415. SPOT 50 SX CL	C PLUG ACROSS CSG SHOE	@ 350 FROM 415-28	7-1730. 85.		
8. PUH TO 30. SPOT 15 SX CL C	PLUG FROM 30 TO SURFACE	E. POOH W/WS.			
9. ND BOP. RD PU. DIG OUT CELL	LAR AND CUT CSG 3 BELOW	SURFACE. WELD ST	EEL PLATE ON	CSG.	
STUB. ERECT P & A MARKER \	WITH WELL NAME AND PLO		dhar & Clean On Must Be i		
			TO THE BEGI		
		ALCGO NO CPE			
		TO BE ASSEDY			
I hereby certify that the information above is true as	nd complete to the best of my knowledge and				
SKINATURE JULY POLLOCT	m	REGULATORY TEC	CHNICIAN	DATE 08-19-93	
TYPE OR PRINT NAME KAYE POLLOCK				(915) TELEPHONE NO. 688–2584	
(This space for State Use) OPIGINAL SIGN	MED BY TEDDY SEYTON				

_ TITLE ___

DISTRICT I SUPERVISOP

APPROVED BY ---