

U. S. Geological Survey
P. O. Box 1157
Hobbs, New Mexico

HOBBS DISTRICT

Operator: Sun Oil Company

Well: No. 1 Jennings Federal "A"

Lease No. New Mexico 025497

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e., ripping of pad and/or access road, reseeding, etc. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.

RECEIVED

APR 12 1977

CH. COMM. & J. COMM.
HDSR, H. M.