

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
reverse side)

E*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 25458

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

--

7. UNIT AGREEMENT NAME

--

8. FARM OR LEASE NAME

Gulf-McKay Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

North Lusk-Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T18S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. OIL ☐ WELL GAS ☒ WELL OTHER

2. NAME OF OPERATOR

Petroleum Development Corporation

3. ADDRESS OF OPERATOR

9720 B Candelaria NE, Albuquerque, NM 87112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1980' FWL

14. PERMIT NO.

--

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3715 KB

3697 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

Workover

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRUPU; load tubing; pull tubing & packer.
2. Re-run tubing with E-Z drill retainer; set retainer at 11630'; squeeze with 100 sx. Class "H" w/CFR-2 and retarder.
3. Run 4-3/4" bit; scraper, 8 drill collars, tubing; drill out:
Retainer & cement - 11630-11700
Retainer & cement: - 11963-12073
Cement and CIBP - 12449-12486
Retainer & cement - 12681-12760
4. Perforate Morrow sands w/4 JSPF; 12691-94; 12718-21; 12727-29; 12734-36; 12744-60.
5. Run tubing, packer, vent assembly. Test to clean up.
6. Acidize with 2000 gallons 7½% MSR acid.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Secretary

DATE

6/7/78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

