

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Revised Edition
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SHUT-IN		5. LEASE DESIGNATION AND SERIAL NO. LC-067230	
2. NAME OF OPERATOR SHELL WESTERN E&P INC.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1730' FEL		8. FARM OR LEASE NAME FEDERAL 3	
14. XXXXXX API NO. 30-025-25701		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3664.7' GR, 3680' KB		10. FIELD AND POOL, OR WILDCAT LUSK BONE SPRING, EAST	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 3, T19S-R2E	
		12. COUNTY OR PARISH LEA	
		13. STATE NEW MEXICO	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) SWAB TEST/STATUS <input checked="" type="checkbox"/>	
(Other) <input type="checkbox"/>		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2-13 to 2-14-86: Had total recovery on two-day swab test of 63 BO + 88 BW. Swabbed well dry last 4 hrs of test. Fluid level remaining @ 8700'. Returned well to shut-in status.

NOTE: Federal 3 #2 was shut-in 1-25-85 to naturally break a possible emulsion block and also to stabilize the well. Shell Western E&P Inc. (SWEPI) wishes to extend this well's shut-in status until July 1, 1986 - the date that Petrus Operating Co. will assume operations. SWEPI has not been informed of any plans that the new operator has for this well.

ACCEPTED FOR RECORD

Shed
JUL 17 1986

CARISBRO, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *A. J. Fore* A. J. FORE TITLE SUPERVISOR REG. & PERMITS DATE JUNE 20, 1986

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side