

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25711
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1113-1
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	100
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER CO2 INJECTION WELL

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter F : 1372 Feet From The NORTH Line and 2544 Feet From The WEST Line
Section 6 Township 18S Range 35E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3972' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ C/O, PERF, STIM

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/13/99: MIRU REV EQPT. RU FLOW LINE & SET BLOW DN TANK. INSTL CHIKE IN WH. FLOW BACK @ 1500 PSI.
10-14-99: PUMP 275 BBLS 10# BRINE TO KILL.
10-15-99: ND TREE. NU BOP. TEST TO 1000#-OK. TRY TO REL INJ PKR. REL ON/OFF TOOL. TIH W/ON/OFF TOOL. BMPR SUB ON WS TO 4220'. LATCH ON PKR & JAR LOOSE.
10-16-99: KILL W/30 BBLS 11# MUD. RECVD PKR. TIH W/BIT ON TBG. TAG @ 4750'-OK. PULL BIT TO 4205'.
10-18-99: INSTL LUBRICATOR & TEST TO 1000#. TIH W/PERF GUN-TAG @ 4421'. TIH W/SNKR BAR & JNK BASKET ON WL. WRK FR 4300-4416'.
10-19-99: TIH W/CSG SWEDGE, BMPR SUB, JARS, DC'S. TAG @ 4316'. SWEDGE OUT TO 4321'. LOWER TOOLS & TAG BTM @ 4750'. TIH W/SWEDGE. TAG @ 4316'. SWEDGE OUT CSG TO 4361'. LOWER TOOLS & TAG @ 4718'. SWEDGE OUT TO 4750'. PULL SWEDGE TO 4120'.
10-20-99: TIH & TAG @ 4750'. INSTL LUB. TEST TO 1000#-OK. TIH W/PERF GUN & PERF VGSA FORMATION 4713-21, 4682-96, 4662-76, 4646-56. TIH W/SHORT CATCH OVERSHOT, BMPR SUB, JARS, DC'S ON TBG TO 4464'.
10-21-99: TIH TO 4464'. WASH 4464-4726'. TIH W/PERF GUN & PERF 4387-92, 4352-57. TIH W/PKR, SN ON TBG & SET PKR @ 4201'.
10-22-99: ACIDIZE PERFS 4217-4721' W/6000 GALS 15% NEFE & 2500# RK SLT. FLOW BACK 333 BBLS.
10-25-99: REL PKR. TIH W/PKR, ON/OFF TOOL & TBG. PSA 10' KB @ 4242'.
10-26-99: REL ON/OFF TOOL. DISPL W12# MUD, W/10# BRINE TRTD WTR. LATCH ONTO PKR @ 4242'. TEST & CHART FOR 30 MIN-OK. LAND TBG. NDBOP. INSTL TREE. TEST SAME TO 2000 PSI-OK. RU INJ LINE. RIG DOWN.
11-03-99: ON 24 HR OPT. INJ'G CO2 2419 MCFPD @ 1794 PSI.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 11/04/1999

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY DAVID WINK TITLE FIELD REP.

DATE 11/04/1999

CONDITIONS OF APPROVAL, IF ANY:

JCS

